


# **PROBLEM SUMMARY**










Machine Id 925025 Component **Diesel Fuel** NOT GIVEN (--- GAL)

# **COMPONENT CONDITION SUMMARY**





## RECOMMENDATION

We advise that you check for the source of coolant entry. We advise that you check the fuel injection system. We advise that you follow the water drainoff procedure for this component. Recommend drain fuel if not already done and flush before refilling with

PROBLEMATI	ATIC TEST RESULTS  SEVERE					
Sample Status				SEVERE	 	
Silicon	ppm	ASTM D5185m	<1.0	<b>9</b> 35	 	

Customer Id: GFL947 **Sample No.:** GFL0082529 Lab Number: 05888589 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Recommend drain fuel if not already done and flush with cleaner before refilling with fuel.		
Flush System			?	Recommend drain fuel if not already done and flush with cleaner before refilling with fuel.		
Water Drain-off			?	We advise that you follow the water drain-off procedure for this component.		
Check Fuel/injector System			?	We advise that you check the fuel injection system.		
Check Water Access			?	We advise that you check for the source of water entry.		


# HISTORICAL DIAGNOSIS



# **FUEL REPORT**



Machine Id 925025 Component **Diesel Fuel NOT GIVEN (--- GAL)** 



Sample Rating Trend



# DIAGNOSIS

#### Recommendation

We advise that you check for the source of coolant entry. We advise that you check the fuel injection system. We advise that you follow the water drainoff procedure for this component. Recommend drain fuel if not already done and flush before refilling with fuel.

## Corrosion

The copper level is abnormal.

### Contaminants

Test for glycol is positive. Excessive free water/antifreeze present.


## **Fuel Condition**


The fuel is no longer serviceable due to the presence of contaminants.

				Jun2023		
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number		Client Info		GFL0082529		
Sample Date		Client Info		26 Jun 2023		
Machine Age	hrs	Client Info		20738		
Sample Status				SEVERE		
SULFUR CONT	ΓENT	method	limit/base	current	history 1	history 2
Sulfur	ppm	ASTM D5185m		111		
CONTAMINAN	TS	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	<1.0	<b>3</b> 5		
Sodium	ppm	ASTM D5185m	<0.1	5820		
Potassium	ppm	ASTM D5185m	<0.1	979		
HEAVY METAL	_S	method	limit/base	current	history 1	history 2
Aluminum	ppm	ASTM D5185m	< 0.1	0		
Lead	ppm	ASTM D5185m	<0.1	5		
Iron	ppm	ASTM D5185m	< 0.1	0		
Calcium	ppm	ASTM D5185m	<0.1	57		
Magnesium	ppm	ASTM D5185m	< 0.1	33		
Phosphorus	ppm	ASTM D5185m	<0.1	35		
Zinc	ppm	ASTM D5185m	< 0.1	1200		
SAMPLE IMAG	iES	method	limit/base	current	history 1	history 2
Color					no image	no image
Bottom					no image	no image



# **FUEL REPORT**









Laboratory Sample No. Lab Number Unique Number : 10539072

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0082529 : 05888589

Received Diagnosed

: 30 Jun 2023 : 11 Jul 2023 Diagnostician : Doug Bogart

Test Package : FLEET ( Additional Tests: Bacteria, KF )

GFL Environmental - 947 - WB Horicon HC N7296 County Rd V Horicon, WI US 53032

Contact: Tim Kieffer tim.kieffer@gflenv.com T: (608)219-0288

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)