


PROBLEM SUMMARY

Sample Rating Trend




Machine Id


FREIGHTLINER 89

Diesel Engine

PETRO CANADA DURON SHP 15W40 (13 LTR)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE	ABNORMAL	SEVERE			
Fuel	%	ASTM D3524	>5	A 8.7	▲ 5.8	▲ 3.4			
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	2.5	6.3	0.0			
Visc @ 100°C	cSt	ASTM D445	15.4	12.0	A 12.3	15.1			

Customer Id: ATRPIN Sample No.: PCA0117381 Lab Number: 06239979 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:


Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	Oil and filter change at the time of sampling has been noted.			
Change Filter			?	Oil and filter change at the time of sampling has been noted.			
Resample			?	We recommend an early resample to monitor this condition.			
Check Fuel/injector System			?	We advise that you check the fuel injection system.			

HISTORICAL DIAGNOSIS

....





The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.



SOOT

28 Sep 2023 Diag: Don Baldridge




We advise that you check for faulty combustion, plugged air filters, or aftercoolers. We recommend an early resample to monitor this condition. NOTE: High solids (carbon/soot) in the sample have limited the accuracy of Infra-Red data including Total Base Number (TBN) value. All component wear rates are normal. There is an abnormal amount of solids and carbon present in the oil. Light fuel dilution occurring. The BN level is low.





OIL ANALYSIS REPORT

Sample Rating Trend





Machine Id

FREIGHTLINER 89

Diesel Engine

PETRO CANADA DURON SHP 15W40 (13 L

DIAGNOSIS

Recommendation

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a high amount of fuel present in the oil.


Fluid Condition

Fuel is present in the oil and is lowering the viscosity. The BN level is low. The oil is no longer serviceable due to the presence of contaminants.

LTR)		Jun202	3 Sep2023	Apr2024 Jr	in2024	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0117381	PCA0115403	PCA0105007
Sample Date		Client Info		27 Jun 2024	18 Apr 2024	28 Sep 2023
Machine Age	mls	Client Info		542975	515162	437944
Oil Age	mls	Client Info		25000	25000	30000
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				SEVERE	ABNORMAL	SEVERE
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	50	47	55
Chromium	ppm	ASTM D5185m	>5	2	2	3
Nickel	ppm	ASTM D5185m	>2	<1	0	<1
Titanium	ppm	ASTM D5185m		0	0	<1
Silver	ppm	ASTM D5185m	>3	0	0	<1
Aluminum	ppm	ASTM D5185m	>30	4	<1	1
Lead	ppm	ASTM D5185m	>30	24	2	21
Copper	ppm	ASTM D5185m	>150	4	12	8
Tin	ppm	ASTM D5185m	>5	2	0	2
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	7	11	7
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	66	58	59
Manganese	ppm	ASTM D5185m	0	1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	214	978	818
Calcium	ppm	ASTM D5185m	1070	1809	1116	1258
Phosphorus	ppm	ASTM D5185m	1150	859	1016	936
Zinc	ppm	ASTM D5185m	1270	937	1220	1228
Sulfur	ppm	ASTM D5185m	2060	3670	3244	3043
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	13	12	8
Sodium	ppm	ASTM D5185m		6	2	<1
Potassium	ppm	ASTM D5185m	>20	5	<1	3
Fuel	%	ASTM D3524	>5	▲ 8.7	△ 5.8	▲ 3.4
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	2.4	2.1	▲ 5.3
Nitration	Abs/cm	*ASTM D7624	>20	12.3	9.4	14.3
Sulfation	Abs/.1mm	*ASTM D7415	>30	31.9	24.3	32.4
FLUID DEGRA	NOITAC	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	26.3	18.7	22.9
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	2.5	6.3	<u> </u>
. ,	- 0					



OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0117381 Lab Number : 06239979 Unique Number : 11128813

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Received Tested

: 18 Jul 2024 Diagnosed Test Package : FLEET (Additional Tests: PercentFuel)

: 19 Jul 2024 : 19 Jul 2024 - Don Baldridge

Pineville, NC US 28134 Contact: Vlad Melnichuk shop@migway.com T: (980)255-3200

9349 China Grove Church Road

 st - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: ATRPIN [WUSCAR] 06239979 (Generated: 07/21/2024 10:57:43) Rev: 1