CONSTRUCTION EQUIPMENT 314854 VOLVO G940 40867 - HYDRAULIC SYSTEM



 Sample No:
 VCP347387

 Oil Type:
 CASTROL HVI 32

 Job No:
 314854

TOTATO

## SAMPLE INFORMATION

Sample Number		VCP347387			
Sample Date		27 May 2022			
Machine Hours		11395			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		SEVERE			
OIL COND					
			<u> </u>	<u>.</u>	
Visc @ 40°C	cSt	31.2			
CONTAMI	ΝΛΤΙΩΝ				
	NATION		-	<u>.</u>	
Particles >4µm		🛑 43415			
Particles >6µm		<u> </u>			
Particles >14µm		<b>16</b>			
ISO 4406:1999 (c)		23/18/11			
Silicon	ppm	5			
Sodium	ppm	2			
Potassium	ppm	<b>1</b>			

VOLVO				
WEAR M	AFTAI S			
			<u>-</u>	
Iron	ppm	<b>12</b>		 
Copper	ppm			 
Lead	ppm	<b></b> <1		 
Tin	ppm	0		 
Aluminum	ppm	2		 
Chromium	ppm			 
Molybdenum	ppm	0		 
Nickel	ppm	0		 
Titanium	ppm	0		 
Silver	ppm	0		 
Manganese	ppm	0		 
Vanadium	ppm	0		 

ADDITIVES					
Calcium	ppm	129			
Magnesium	ppm	2			
Zinc	ppm	337			
Phosphorus	ppm	304			
Barium	ppm	0			
Boron	ppm	<b>1</b>			



## STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW Acheson, AB CA T7X 6C2 Contact: Jason Sweet jsweet@strongco.com T: Phone F: (780)417-2615

## Diagnosis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. Particles >4µm and oil cleanliness are severely high. Particles >6µm are notably high. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

Depot:	VOLVO3908
Unique No:	5410030
Signed:	Kevin Marson
Report Date:	08 Jun 2022

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO

