

CONSTRUCTION EQUIPMENT 375379 VOLVO A25F 80028 - TRANSMISSION (AUTO)



Sample No: VCP392456
Oil Type: VOLVO AT 102

Job No: 375379

SAMPLE	INFORMATIO	N		
Sample Number		VCP392456	 	
Sample Date		15 Aug 2023	 	
Machine Hours		16156	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	NITION			
Visc @ 40°C	cSt	<u>▲</u> 66.0	 	
VISC @ 40 C	CSL	<u> </u>	 	
VOLVO				
CONTAN	MINATION			
Silicon	ppm	■ 3	 	
Sodium	ppm	1	 	
Potassium	ppm	-<1	 	
WEAR N	METALS			
Iron	ppm	1 6	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	9	 	
Tin	ppm	■ 9	 	
Aluminum	ppm	6	 	
Chromium	ppm	■ 0	 	
Molybdenum	ppm	1	 	
Nickel	ppm	■<1	 	
Titanium	ppm	<1	 	
Silver	ppm	<u>^</u> 6	 	
Manganese	ppm		 	
Vanadium	ppm	0	 	
VOLVO			 	
ADDITIV	/ES			
Calcium	ppm	<u> </u>	 	
Magnesium	ppm	■10	 	
Zinc	ppm	<u>▲</u> 638	 	
Phosphorus	ppm	■650	 	
Barium	ppm	■0	 	
Boron	ppm	40	 	
		_		



STRONGCO EQUIPMENT

54 IBER ROAD OTTAWA, ON CA K2S 1E8 Contact: Daniel Simard dsimard@strongco.com T: (613)836-6633 F: (613)836-2614

Diagnosis

The fluid change at the time of sampling has been noted. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Silver and copper ppm levels are abnormal. Clutch disc wear or oil cooler leaching indicated. There is no indication of any contamination in the fluid. Viscosity of sample indicates oil is within SAE 30 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:SHESTIUnique No:5629539Signed:Kevin MarsonReport Date:18 Aug 2023



CONSTRUCTION EQUIPMENT





GRAPHS

