

Sample No: VCP392462
Oil Type: NOT GIVEN

Job No:

VOLVO	INFORMATIO	N		
	INFUKMATIU			_
Sample Number		VCP392462	 	
Sample Date		16 Aug 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		SEVERE	 	
VOLVO				
OIL CONI	NITION			
Visc @ 40°C		153	 	
	cSt	153	 	
VOLVO				
CONTAM	IINATION			
Silicon	ppm	0 70	 	
Sodium	ppm	16	 	
Potassium	ppm	12	 	
	pp			
VOLVO				
WEAR M	IF LAT7			
Iron	ppm	140	 	
Copper	ppm	<u>▲</u> 55	 	
Lead	ppm	9	 	
Tin	ppm	■<1	 	
Aluminum	ppm	42	 	
Chromium	ppm	2	 	
Molybdenum	ppm	1	 	
Nickel	ppm	0	 	
Titanium	ppm	1	 	
Silver	ppm	<1	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITIV	FC			
		25.5		
Calcium	ppm	2553	 	
Magnesium	ppm	42	 	
Zinc	ppm	506	 	
Phosphorus	ppm	677	 	
Barium	ppm	1	 	
Boron	ppm	9	 	



STRONGCO EQUIPMENT

54 IBER ROAD OTTAWA, ON CA K2S 1E8 Contact: Andrew Mclean amclean@strongco.com T: (613)836-6633 F: (613)836-2614

Diagnosis

We advise that you check all areas where dirt can enter the system. We recommend that you drain the oil from the component if this has not already been done. We advise that you flush the component thoroughly before re-filling with oil. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.Copper ppm levels are abnormal. Aluminum ppm levels are noted. Bearing and/or bushing wear is indicated. We have assumed that this component is not breaking in (age of component not reported). Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. High amount of ingressed dirt has caused abrasive wear to the component. Viscosity of sample indicates oil is within SAE 50 range, advise investigate. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:SHESTIUnique No:5629566Signed:Kevin MarsonReport Date:18 Aug 2023



CONSTRUCTION EQUIPMENT





