



CONSTRUCTION EQUIPMENT

379672 16-8008 - TRANSMISSION (AUTO)



Sample No: VCP391624
Oil Type: VOLVO EXTRA AUTOMATIC FLUID
Job No: 379672



SAMPLE INFORMATION

Sample Number	VCP391624	VCP394714	VCP391764	VCP353248
Sample Date	29 Sep 2023	15 Jul 2023	02 May 2023	20 Nov 2022
Machine Hours	10500	10000	9499	9077
Oil Hours	2500	2000	1500	1000
Oil Changed	Not Chngd	Not Chngd	Not Chngd	Not Chngd
Sample Status	ABNORMAL	NORMAL	NORMAL	NORMAL

CRH CANADA GROUP INC.

P.O. BOX 5400
 CONCORD, ON
 CA L4K 1B6
 Contact: Dan Brown
 dan.brown@ca.crh.com



OIL CONDITION

Visc @ 40°C	cSt	27.7	27.9	27.9	28.1
-------------	-----	------	------	------	------



CONTAMINATION

Silicon	ppm	6	6	6	6
Sodium	ppm	3	3	2	2
Potassium	ppm	4	1	4	4



WEAR METALS

PQ		0	---	---	---
Iron	ppm	▲ 161	56	112	109
Copper	ppm	5	11	3	3
Lead	ppm	<1	0	<1	0
Tin	ppm	0	0	0	0
Aluminum	ppm	<1	5	<1	<1
Chromium	ppm	0	<1	0	0
Molybdenum	ppm	0	0	0	0
Nickel	ppm	<1	<1	0	<1
Titanium	ppm	0	0	0	0
Silver	ppm	<1	0	0	0
Manganese	ppm	1	2	2	2
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	135	73	144	142
Magnesium	ppm	<1	2	<1	2
Zinc	ppm	32	34	32	34
Phosphorus	ppm	200	208	226	221
Barium	ppm	<1	<1	0	0
Boron	ppm	71	65	71	72

Diagnosis

We recommend that you drain the fluid from the component if this has not already been done. We recommend an early resample to monitor this condition. Iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. There is no indication of any contamination in the fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

Depot: HOLCON
Unique No: 5657731
Signed: Kevin Marson
Report Date: 12 Oct 2023

VOLVO **GRAPHS**

