

CONSTRUCTION EQUIPMENT

381835 XCMG XE360U THKAOO106 - REAR RIGHT FINAL DRIVE

 Sample No:
 VCP352604

 Oil Type:
 SAE 80W90

 Job No:
 381835

VOLVO					
SAMPLE	INFORMATIO	N			
Sample Number	-	VCP352604			
Sample Date		14 Nov 2023			
Machine Hours		4022			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		ABNORMAL			
OIL CON	NITION				
Visc @ 40°C	cSt	43.4			
VOLVO					
CONTAM	IINATION				
Water	%	NEG			
Silicon	ppm	▲ 821			
Sodium	ppm	■39			
Potassium	ppm	45			
rotassiani	PPIII				
VOLVO					
WEAR M	ETALS				
PQ		<u></u> 881			
Iron	ppm	<u> </u>			
Copper	ppm	6			
Lead	ppm	■<1			
Tin	ppm	■2			
Aluminum	ppm	<u> </u>			
Chromium	ppm	<u> </u>			
Molybdenum	ppm	■ 2			
Nickel	ppm	<u> </u>			
Titanium	ppm	<u>▲</u> 12			
Silver	ppm	<1			
Manganese	ppm	■20			
Vanadium	ppm	<1			
VOLVO					
ADDITIV	ES				
Calcium	ppm	2200			
Magnesium	ppm	■ 68			
Zinc	ppm	1019			
Phosphorus	ppm	■800			
Barium	ppm	7			
Boron	ppm	□ 12			
_ 0.0	PP.11				



STRONGCO EQUIPMENT-EDMONTON

25616 117 Ave NW Acheson, AB CA T7X 6C2 Contact: Jason Sweet jsweet@strongco.com T: Phone F: (780)417-2615

Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Confirm the source of the lubricant being utilized for topup/fill. We recommend an early resample to monitor this condition. The fluid was specified as (GENERIC) SAE 80W90, however, a fluid match indicates that this fluid is SAE 10W Transmission/Drive Train Oil. Please confirm the oil type and grade on your next sample.PQ levels are abnormal. Chromium and iron and nickel ppm levels are abnormal. Aluminum ppm levels are noted. Titanium ppm levels are marginal. Gear wear is indicated. The high ferrous density (PQ) index indicates that abnormal wear is occurring. Elemental levels of silicon (Si) and aluminum (Al) indicate aluminasilicate (coarse dirt) ingress. High amount of ingressed dirt has caused abrasive wear to the component. Viscosity of sample indicates oil is within SAE 10W range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:VOLVO3908Unique No:5694099Signed:Kevin MarsonReport Date:07 Dec 2023



CONSTRUCTION EQUIPMENT





