

## CONSTRUCTION EQUIPMENT

X10214 WCA001 VOLVO EC300DL 210381 - LEFT FINAL DRIVE

Sample No: VCP423452
Oil Type: NOT GIVEN

**Job No:** X10214 WCA001

SAMPLE SAMPLE	INFORMATIO	N			
	IIII OIII-III II		_	·	
Sample Number		VCP423452			
Sample Date		26 May 2023			
Machine Hours		6326			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		SEVERE			
VOLVO					
OIL CON	DITION				
Visc @ 40°C	cSt	<b>549</b>			
VI3C @ 40 C	CSC				
VOLVO					
CONTAM	IINATION				
Water	%	2.76			
Silicon	ppm	<b>10000</b>			
Sodium	ppm	■81			
Potassium	ppm	<b>■349</b>			
VOLVO					
WEAR M	F1YT7				
Iron	ppm	<b>10000</b>			
Copper	ppm	<b>19</b>			
Lead	ppm	<b>3</b>			
Tin	ppm	<b>■7</b>			
Aluminum	ppm	<b>1000</b>			
Chromium	ppm	<b>131</b>			
Molybdenum	ppm	19			
Nickel	ppm	<b>13</b>			
Titanium	ppm	<b>118</b>			
Silver	ppm	_ <1			
Manganese	ppm	111			
Vanadium	ppm	5			
	PP				
VOLVO					
ADDITIV	FZ				
Calcium	ppm	193			
Magnesium	ppm	143			
Zinc	ppm	15			
Phosphorus	ppm	549			
Barium	ppm	16			
Boron	ppm	57			



SCOTT EQUIPMENT COMPANY LLC - Texarkana 5401 SANDERSON LANE TEXARKANA, AR US 71854 Contact: JAMES DOSS jdoss@scottcompanies.com T:

F:

## Diagnosis

We advise that you check for the source of water entry. We advise that you check all areas where dirt can enter the system. We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. The iron and chrome levels are severe. Gear wear is indicated. There is a high concentration of water present in the oil. Elemental levels of silicon (Si) and aluminum (Al) indicate aluminasilicate (coarse dirt) ingress. The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO1034Unique No:10508068Signed:Don BaldridgeReport Date:12 Jun 2023



## **CONSTRUCTION EQUIPMENT**





