CONSTRUCTION EQUIPMENT SW1013505 THRONDORED JCB 506C 1184387 - TRANSMISSION

Sample No:VCP397624Oil Type:TDTO FLUID SAE 10WJob No:SW1013505 THRONDORED

VOLVO

ADDITIVES

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Sample Number		VCP397624	VCP342558	
Sample Date		23 Jun 2023	03 Dec 2021	
Machine Hours		0	0	
Oil Hours		0	0	
Oil Changed		Not Changd	Changed	
Sample Status		ABNORMAL	ABNORMAL	
OIL CON				
		· · · ·	-	
Visc @ 40°C	cSt	39.2	40.2	
VOLVO				
CONTAN	AINATION			
Silicon	ppm	7	7	
Sodium	ppm	<1	<1	
Potassium	ppm	0	0	
			_	
VOLVO	AFTALS			
V WEAR N	AE I ALS		<u>_</u>	
Iron	ppm	28	58	
Copper	ppm	<u> </u>	▲ 554	
Lead	ppm	0	2	
Tin	ppm	0	 <1	
Aluminum	ppm	0	1	
Chromium	ppm		<1	
Molybdenum	ppm	□<1	 <1	
Nickel	ppm	0	0	
Titanium	ppm	0	<1	
Silver	ppm	0	<1	
Manganese	ppm	2	3	
Vanadium	ppm	0	0	

2844

10

924

792

0

15

ARNOLD MACHINERY COMPANY 4323 EAST WINSLOW AVENUE PHOENIX, AZ

US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level has decreased, but is still abnormal. Clutch disc wear or oil cooler leaching indicated. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:	VOLVO6174	
Unique No:	10538599	
Signed:	Don Baldridge	
Report Date:	04 Jul 2023	

3330

1095

868

9

0


0

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Contact/Location: RANDY PRZEKURAT - VOLVO6174