

Sample No: VCP424463

Oil Type: VOLVO WB 102

Job No: 579198 APTIM

SAMPLE	INFORMATION			
Sample Number		VCP424463	VCP424848	
Sample Date		11 Jul 2023	16 Mar 2023	
Machine Hours		8937	8480	
Oil Hours		4000	3000	
Oil Changed		Changed	Not Changd	
Sample Status		ABNORMAL	ABNORMAL	
OIL CON	DITION			
Visc @ 40°C	cSt	□48.4	1 49.1	
VOLVO				
CONTAM	IINATION			
Silicon	ppm	■ 9	1 0	
Sodium	ppm	■ 3	3	
Potassium	ppm	0	< 1	
WEAR M	IETALS			
ron	ppm	□27	2 4	
Copper	ppm	<u>^</u> 246	<u>^</u> 245	
Lead	ppm	■ 3	 <1	
Tin	ppm	<u> </u>	0	
Aluminum	ppm	O	■ <1	
Chromium	ppm	■<1	- <1	
Molybdenum	ppm	2	2	
Nickel	ppm	3	3	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	1	2	
Vanadium	ppm	<1	0	
	- - · · ·			
VOLVO	IP.C			
ADDITIV	F2			
Calcium	ppm	■2664	2797	
Magnesium	ppm	13	1 6	
Zinc	ppm	1150	1203	
Phosphorus	ppm	1021	■1046	
Barium	ppm	0	0	
Boron	ppm	60	60	
	-			



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: JOHN FARDELLA
JFARDELLA@ALTAEQUIPFL.COM
T: (813)630-0077
F: (813)630-2233

Diagnosis

The fluid change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0093Unique No:10564861Signed:Don BaldridgeReport Date:24 Jul 2023



CONSTRUCTION EQUIPMENT





GRAPHS

