

Sample No: VCP398757 **Oil Type:** VOLVO WB 102

Job No: 295157-10

VOLVO	E INFORMATION			
_	INFURMATION	<u>.</u>		
Sample Number		VCP398757	VCP353581	
Sample Date		17 Aug 2023	09 Sep 2022	
Machine Hours		5046	3066	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	ABNORMAL	
OIL CON	DITION			
Visc @ 40°C	cSt	27.1	□ 26.2	
Visc & 10 C	CSt			
VOLVO				
CONTAI	MOITANIN			
Silicon	ppm	6	1 1	
Sodium	ppm	7	5	
Potassium	ppm	1	■3	
VOLVO	ACTAL C			
WEAR N	NE I ALZ			
Iron	ppm	135	<u> </u>	
Copper	ppm	12	1 0	
Lead	ppm	0	0	
Tin	ppm	■ 0	0	
Aluminum	ppm	1	2	
Chromium	ppm	■<1	- <1	
Molybdenum	ppm	■0	<1	
Nickel	ppm	-<1	0	
Titanium	ppm	0	0	
Silver	ppm	■ 0	0	
Manganese	ppm	6	10	
Vanadium	ppm	0	0	
VOLVO	ILC			
ADDITIV	VEZ.			
Calcium	ppm	■88	116	
Magnesium	ppm	1	3	
Zinc	ppm	54	62	
Phosphorus	ppm	202	189	
Barium	ppm	0	0	
Boron	ppm	55	58	



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC 9601 BOGGY CREEK RD

9601 BOGGY CREEK RD ORLANDO, FL US 32824 Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736 F: (407)659-8720

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The wear metal levels do not reflect the reported failure. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0096Unique No:10616467Signed:Don BaldridgeReport Date:23 Aug 2023



CONSTRUCTION EQUIPMENT





