

CONSTRUCTION EQUIPMENT SWA307696-10 VOLVO A40G 342584 - DROP BOX



Sample No: VCP418836

Oil Type: VOLVO API GL-5 SAE 75W90

Job No: SWA307696-10

| CVMDIE | INFORMATION | | | | |
|----------------------|----------------|---------------|----------------|-------------|--------------|
| | . INI UNMATION | VCP418836 | VCP294959 | VCP294505 | VCP279494 |
| Sample Number | | | | | |
| Sample Date | | 19 Aug 2023 | 19 Jun 2021 | 11 Feb 2021 | 14 Oct 2020 |
| Machine Hours | | 8359 | 3832 | 3516 | 3033 |
| Oil Hours | | 0 | | 500 | 3000 |
| Oil Changed | | N/A | Not Changd | Not Changd | Changed |
| Sample Status | | SEVERE | ABNORMAL | NORMAL | ATTENTION |
| VOLVO | | | | | |
| OIL CON | DITION | | | | |
| Visc @ 40°C | cSt | ▲ 58.9 | 114 | 115 | <u>45.4</u> |
| | | | _ | _ | |
| VOLVO | AIN A TION | | | | |
| _ | MINATION | | | | |
| Silicon | ppm | 7 | 9 | ■8 | ■37 |
| Sodium | ppm | ■<1 | 4 | 4 | 1 1 |
| Potassium | ppm | ■<1 | < 1 | 1 | 2 |
| | | | | | |
| WEAR N | METALS | | | | |
| Iron | ppm | 1454 | □ 60 | 1 73 | □ 160 |
| Copper | ppm | 10 | 3 | 2 | □12 |
| Lead | ppm | ■0 | - <1 | 0 | - <1 |
| Tin | ppm | ■<1 | 0 | 0 | - <1 |
| Aluminum | ppm | 7 | □ 9 | 1 5 | ■19 |
| Chromium | ppm | 13 | 2 | 2 | 2 |
| Molybdenum | ppm | 5 | ■8 | ■8 | ■8 |
| Nickel | ppm | 10 | - <1 | | - <1 |
| Titanium | ppm | 0 | 0 | 0 | <1 |
| Silver | ppm | 0 | <1 | <1 | 0 |
| Manganese | ppm | 17 | 2 | 1 | 5 |
| Vanadium | ppm | 0 | 0 | 0 | 0 |
| | | | | | |
| ADDITIV | /FC | | | | |
| Calcium | - | <u></u> | 1 3 | 10 | <u></u> |
| Magnesium | ppm | 0 | <1 | 0 | 2 |
| Zinc | ppm | <u> </u> | □ < I □ 18 | □ 17 | ■ 2 |
| | ppm | △ 2126 | □ 18 □ 1239 | 1208 | 2112 |
| Phosphorus Barium | ppm | | | _ | |
| | ppm | ■ 0 | 0 | 0 | 0 |
| Boron | ppm | 102 | 239 | 162 | 149 |



THALLE INDUSTRIES

172 ROUTE 9
FISHKILL, NY
US 12524
Contact: M SANTIAGO
msantiago@thalleindustries.com
T: (845)896-5156
F: (845)896-0161

Diagnosis

We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Additive levels indicate the addition of a different brand, or type of oil. Confirm oil type. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:THAFISUnique No:10617662Signed:Jonathan HesterReport Date:25 Aug 2023



CONSTRUCTION EQUIPMENT





