

## **CONSTRUCTION EQUIPMENT**

W07013503-1 MINORITY VOLVO L50H 4323144 - DIESEL ENGIN

Sample No: VCP409364

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Silver

Oil Type: DIESEL ENGINE OIL SAE 15W40

**Job No:** W07013503-1 MINORITY

CAMPI F II	NFORMATION			
	NI OMPATION		 	<u>.</u>
Sample Number		VCP409364	 	
Sample Date		09 Oct 2023	 	
Machine Hours		536	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ATTENTION	 	
OIL CONDI	TION			
Visc @ 100°C	cSt	<b>10.8</b>	 	
Base Number (BN)	mg KOH/g	<b>■7.9</b>	 	
Oxidation (PA)	%	78	 	
VOLVO	MATION			
CONTAMI			 	
Soot %	%	■ 0.4	 	
Nitration (PA)	%	68	 	
Sulfation (PA)	%	60	 	
Glycol	%	NEG	 	
Fuel	%	<b>1.4</b>	 	
Silicon	ppm	■33	 	
Sodium	ppm	<b>5</b>	 	
Potassium	ppm	<b>1</b>	 	
WEAR ME	TAIC			
_	IALS		 	
Iron	ppm	■97	 	
Copper	ppm	<b>22</b>	 	
Lead	ppm	■2	 	
Tin	ppm	<b>4</b>	 	
Aluminum	ppm	<b>23</b>	 	
Chromium	ppm	<b>■</b> 9	 	
Molybdenum	ppm	■36	 	
Nickel	ppm	<b>■&lt;1</b>	 	



MCCLUNG-LOGAN EQUIPMENT CO - RICHMOND
1345 MOUNTAIN ROAD
GLEN ALLEN, VA
US 23060
Contact: KYLE RATLIFFE
KRATLIFFE@MCCLUNG-LOGAN.COM
T:

F: (804)266-1611

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. Fuel content negligible. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot:VOLVO8882Unique No:10697598Signed:Don BaldridgeReport Date:18 Oct 2023

**-<1** 

**■**0

**7** 

**1421** 

**560** 

**1047** 

**868** 

**5** 

**45** 

ppm

**ADDITIVES** 



## **CONSTRUCTION EQUIPMENT**





