

## **CONSTRUCTION EQUIPMENT**

19621 TGP CATERPILLAR 345BL AGSO1373 - LEFT SWING DRIVE

Sample No: VCP430757
Oil Type: NOT GIVEN
Job No: 19621 TGP

SAMPLE	INFORMATIO	N		
Sample Number	_	VCP430757	 	
Sample Date		02 Oct 2023	 	
Machine Hours		6400	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		SEVERE	 	
OIL CON	NITINN			
		-450		
Visc @ 40°C	cSt	<b>156</b>	 	
VOLVO				
CONTAN	MINATION			
Water	%	1.60	 	
Silicon	ppm	<b>48</b>	 	
Sodium	ppm	■3	 	
Potassium	ppm	<b>■</b> 5	 	
WEAR	AETAL C			
	JE I WF7			
Iron	ppm	■ 275	 	
Copper	ppm	<b>17</b>	 	
Lead	ppm	<b>1</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>11</b>	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum	ppm	1	 	
Nickel	ppm	<b></b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	2		
Vanadium	ppm	<1	 	
VOLVO				
ADDITIV	ES			
Calcium	ppm	2855	 	
Magnesium	ppm	93	 	
Zinc	ppm	1329	 	
Phosphorus	ppm	1041	 	
Barium	ppm	<1	 	
Boron	ppm	9	 	



117 - ASCENDUM MACHINERY INC - GREENVILLE 2002 N GREENE ST GREENVILLE, NC US 27834 Contact: BRANDON JENKINS BRANDONJENKINS@ASCENDUMMACHINERY.COM T:

F: (704)494-8197

## Diagnosis

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. There is a high concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO8769Unique No:10702383Signed:Don BaldridgeReport Date:24 Oct 2023



## **CONSTRUCTION EQUIPMENT**





