

CONSTRUCTION EQUIPMENT VOLVO A40G 353294 - DIESEL ENGINE RYAN GOLF



Sample No: VCP432467 Oil Type: **NOT GIVEN** Job No: **RYAN GOLF**

	1117111 0021			
VOLVO				
SAMPLE II	NFORMATION			
Sample Number	-	VCP432467	 	
Sample Date		16 Oct 2023	 	
Machine Hours		1215	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
OIL CONDI	TION			
	_	=10.6	 	
Visc @ 100°C	cSt	10.6	 	
Base Number (BN)		■3.3	 	
Oxidation (PA)	%	77	 	
VOLVO				
CONTAMI	NATION			
Soot %	%	■ 0.5	 	
Nitration (PA)	%	73	 	
Sulfation (PA)	%	69	 	
Glycol	%	NEG	 	
Fuel	%	■ 0.8	 	
Silicon	ppm	<u>^</u> 26	 	
Sodium	ppm	6	 	
Potassium	ppm	■ 5	 	
WEAR ME	7147			
_		= 20	 	
Iron	ppm	28	 	
Copper	ppm	<u>^</u> 148	 	
Lead	ppm	1	 	
Tin	ppm	4	 	
Aluminum Chromium	ppm	2	 	
Molybdenum	ppm	■ <1	 	
Nickel	ppm	■ 57	 	
Titanium	ppm	0		
Silver	ppm	0	 	
Manganese	ppm	4	 	
Vanadium	ppm	0	 	
variauluiti	ppm			
VOLVO				
ADDITIVE				
Calcium	ppm	1200	 	
Magnesium	ppm	261	 	
Zinc	ppm	■ 1008	 	
Phosphorus	ppm	■895	 	
Barium	ppm	0	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA john.fardella@altg.com T: (813)630-0077 F: (813)630-2233

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other component wear rates are normal. Fuel content negligible. Elemental level of silicon (Si) above normal indicating ingress of seal material. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: VOLVO0093 **Unique No:** 10723676 Signed: Don Baldridge Report Date: 03 Nov 2023

ppm

Boron



CONSTRUCTION EQUIPMENT





