CONSTRUCTION EQUIPMENT

DIAMONDBACK SERVICES YANMAR VI055-6A JAH464 - DIESEL EI

Sample No:VCP401448Oil Type:NOT GIVENJob No:DIAMONDBACK SERVICES

VOLVO

Sample Number		VCP401448	 	
Sample Date		15 Nov 2023	 	
Machine Hours		1967	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
OIL CON				
Visc @ 100°C	cSt	12.0	 	
Base Number (BN		7.3	 	
Oxidation (PA)	%	78	 	
	<i>,</i> ,,	10		
VOLVO				
CONTAM	INATION			
Water	%	NEG	 	
Soot %	%	0.4	 	
Nitration (PA)	%	78	 	
Sulfation (PA)	%	62	 	
Glycol	%	NEG	 	
Fuel	%	6 .5	 	
Silicon	ppm	15	 	
	ppm	4	 	
Sodium				

WEAR M	METALS			
Iron	ppm	4 9	 	
Copper	ppm	5	 	
Lead	ppm	 <1	 	
Tin	ppm	 <1	 	
Aluminum	ppm	1 2	 	
Chromium	ppm		 	
Molybdenum	ppm	45	 	
Nickel	ppm	0	 	
Titanium	ppm	 <1	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	1619				
Magnesium	ppm	201				
Zinc	ppm	1050				
Phosphorus	ppm	798				
Barium	ppm	0				
Boron	ppm	252				

ROMCO INC

1350 NE LOOP 820 FORT WORTH, TX JS 76106 Contact: CHRIS BITNER CBitner@romco.com T: F: (817)626-8983

Diagnosis

We advise that you check the fuel injection system. Resample at the next service interval to monitor.All component wear rates are normal. The wear metal levels do not reflect the reported failure. There is a moderate amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity.

 Depot:
 VOLVO0081

 Unique No:
 10753839

 Signed:
 Doug Bogart

 Report Date:
 07 Dec 2023


Contact/Location: CHRIS BITNER - VOLVO0081

CONSTRUCTION EQUIPMENT



🎾 GRAPHS

VOLVO



Report Id: VOLVO0081 [WUSCAR] 06014695 (Generated: 12/08/2023 01:42:45) Rev: 1

Contact/Location: CHRIS BITNER - VOLVO0081