

CONSTRUCTION EQUIPMENT

SW0-068518 TAKEUCHI TL6 406002994 - DIESEL ENGINE

Sample No: VCP447596

Oil Type: NOT GIVEN

Job No: SWO-068518

VOLVO	NEODMATION			
	NFORMATION			_
Sample Number		VCP447596	VCP380770	
Sample Date		27 Dec 2023	16 Jan 2023	
Machine Hours		1840	674	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		ABNORMAL	NORMAL	
OIL CONDI	TION			
Visc @ 100°C	cSt	12.4	□13.6	
Base Number (BN)	mg KOH/g	■8.8	9.3	
Oxidation (PA)	%	86	76	
CONTAMIN	IATION			
_				
Water	%	NEG	NEG	
Soot %	%	0.7	□ 0.4	
Nitration (PA)	%	88	83	
Sulfation (PA)	%	64	62	
Glycol	%	NEG	NEG	
Fuel	%	<u>▲</u> 5.4	<1.0	
Silicon	ppm	12	1 0	
Sodium	ppm	■ 3	8	
Potassium	ppm	2	□ 16	
WEAR ME	TALS			
Iron	ppm	■35	4 2	
Copper	ppm	6	■58	
Lead	ppm		5	
Tin	ppm	■<1	1	
Aluminum	ppm	4	5	
Chromium	ppm	1	2	
Molybdenum	ppm	5 4	□74	
Nickel	ppm	■ <1	1	
Titanium	ppm	<1	<1	
Silver	ppm	■ 0	П0	
Manganese	ppm	<1	1	
Vanadium	ppm	0	0	
ADDITIVE:				
Calcium	ppm	1390	1333	
Magnesium	ppm	■819	1108	

1473



WHITAKER CONTRACTING

692 CONVICT CAMP RD

GUNTERSVILLE, AL
US 35976
Contact: BROTHER WHITAKER
BrotherWhitaker@whitaker-contracting.com
T: (256)298-3905
F:

Diagnosis

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 30 Diesel Engine Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample.All component wear rates are normal. There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

Depot:WHIGUNUnique No:10809263Signed:Wes DavisReport Date:04 Jan 2024

ppm

ppm

ppm

ppm

1237

997

0

Zinc

Barium

Boron

Phosphorus



CONSTRUCTION EQUIPMENT





