

CONSTRUCTION EQUIPMENT

SW0-068407 VOLVO EC380EL 310021 - SWING DRIVE



Sample No: VCP428702

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: SWO-068407

SAMPLE	INFORMATION				
Sample Number	-	VCP428702	VCP428933	VCP407511	VCP356243
Sample Date		21 Dec 2023	07 Sep 2023	18 May 2023	03 Nov 2022
Machine Hours		10648	10247	9662	9133
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Not Changd	Changed
Sample Status		SEVERE	SEVERE	SEVERE	SEVERE
OIL CONE	NITION				
Visc @ 40°C	cSt	267	278	□ 264	247
	CSL	20 /	<u></u> 2/0	<u></u>	<u> </u>
VOLVO					
CONTAM	INATION				
Water	%	3.25	6.80	5.11	2.05
Silicon	ppm	16	2 6	■32	1 9
Sodium	ppm	■ 0	5	7	5
Potassium	ppm	■0	6	2	- <1
WEAR M	ETALS				
		= 202		- 422	= 200
Iron	ppm	302	524	423	309
Copper	ppm	<u> </u>	▲ 114	<u> 109</u>	<u>▲</u> 86
Lead	ppm	0	2	<1	1
Tin	ppm	0	2	0	<1
Aluminum	ppm	5	7	1 2	7
Chromium	ppm	1	8	7	5
Molybdenum	ppm	0	4	4	3
Nickel	ppm	0		1	<1
Titanium	ppm	0	<1	<1	<1
Silver	ppm	0	0	0	0
Manganese	ppm	2	12	10	7
Vanadium	ppm	0	<1	<1	0
VOLVO					
ADDITIV	ES				
Calcium	ppm	■83	120	108	□94
Magnesium	ppm	14	23	□21	■18
Zinc	ppm	187	235	211	■180
Phosphorus	ppm	■877	878	■841	763
Barium	ppm	5	0	3	0
Boron	ppm	79	125	111	■89



WHITAKER CONTRACTING

692 CONVICT CAMP RD GUNTERSVILLE, AL US 35976

Contact: BROTHER WHITAKER BrotherWhitaker@whitaker-contracting.com T: (256)298-3905

F:

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The copper level is abnormal. All other component wear rates are normal. Appearance is milky. There is a high concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot:WHIGUNUnique No:10809843Signed:Jonathan HesterReport Date:04 Jan 2024



CONSTRUCTION EQUIPMENT





