

# CONSTRUCTION EQUIPMENT CATERPILLAR D8T JKPZ03752 - DIESEL ENGINE



Sample No: VCP431637

Oil Type: CAT DEO ULS 15W40

Job No:

VOLVO					
	NFORMATION				
Sample Number		VCP431637	VCP404567	VCP355259	VCP350980
Sample Date		15 Jan 2024	19 Dec 2023	09 Jan 2023	26 Sep 2022
Machine Hours		0	10487	9733	9437
Oil Hours		25	459	296	298
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		SEVERE	SEVERE	ABNORMAL	ABNORMAL
OIL CONDI	TION				
Visc @ 100°C	cSt	<b>15.8</b>	<b>□</b> 14.5	□13.1	<b>12.7</b>
Base Number (BN)		10.6	15.3	9.6	10.3
Oxidation (PA)	%	40	51	75	78
SAGGRETATION (171)	.0		J.	, ,	, 0
VOLVO	IATION -				
CONTAMIN					
Water	%	NEG	NEG	NEG	NEG
Soot %	%	■0	□ 0.2	□ 0.4	□ 0.5
Nitration (PA)	%	53	74	58	63
Sulfation (PA)	%	44	48	61	66
Glycol	%	0.10	0.20	NEG	NEG
Fuel	%	<1.0	<1.0	<1.0	<1.0
Silicon	ppm	<b>□</b> 7	<b>2</b> 1	<b>△</b> 32	<b>△</b> 33
Sodium	ppm	<u> </u>	<u>^</u> 200	<b>2</b>	<b>1</b>
Potassium	ppm	<b>△</b> 671	<u> </u>	<b></b> <1	<b>0</b>
VOLVO					
WEAR ME	TALS				
Iron	ppm	<b>7</b>	<b>2</b> 7	<b>1</b> 6	<b>1</b> 8
Copper	ppm	<b>△</b> 566	<b>4</b> 45	<b>5</b>	■8
Lead	ppm	<b>■8</b>	<b>1</b> 4	<b>1</b>	<b>1</b>
Tin	ppm	<b>■&lt;1</b>	<b>-</b> <1	<b>-</b> <1	<b>1</b>
Aluminum	ppm	<b>2</b>	<b>2</b>	<b>2</b>	<b>1</b>
Chromium	ppm	<b>■</b> 0	<b></b> <1	<b>-</b> <1	<b></b> <1
Molybdenum	ppm	<b>103</b>	<b>212</b>	46	■40
Nickel	ppm	<b>■</b> 0	<b>-</b> <1	<b>-</b> <1	<b>0</b>
Titanium	ppm	<b>■&lt;1</b>	<b>-</b> <1	<b>0</b>	<b>0</b>
Silver	ppm	<b>■</b> 0	<b>0</b>	□ 0	<b>0</b>
Manganese	ppm	<b>■&lt;1</b>	<b>1</b>	<1	<b></b> <1
Vanadium	ppm	<1	<1	0	0
VOLVO					
ADDITIVE	2				
Calcium	ppm	<b>1987</b>	□1657	1802	<b>1797</b>
Magnesium	ppm	<b>96</b>	192	466	<b>413</b>
Zinc	ppm	<b>1098</b>	■ 1046	■ 1154	<b>1117</b>
Phosphorus	ppm	<b>955</b>	877	□946	■893
Barium	ppm	<b>■</b> <1	<b>0</b>	0	0
Boron	ppm	<b>9</b>	22	57	<b>□</b> 58
_ 5. 5	PP	-		J.	



#### **COVANTA ENERGY**

141 CRANBERRY HWY
WEST WAREHAM, MA
US 02576
Contact: SAWYER
ssawyer@woodcomachinery.com
T:
F:

### Diagnosis

We advise that you check for the source of the coolant leak. Check for low coolant level. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). Sodium and/or potassium levels are high. There is a high concentration of glycol present in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot:COVWESUnique No:10836664Signed:Angela BorellaReport Date:23 Jan 2024

Contact/Location: ? SAWYER - COVWES



## **CONSTRUCTION EQUIPMENT**





