

CONSTRUCTION EQUIPMENT FORD F550 428 - HYDRAULIC SYSTEM



Sample No:VCP303412Oil Type:{unknown}

Job No:

Sample Number	NFORMATION	VCP303412		
Sample Date		18 Jan 2024		
Machine Hours		0		
Oil Hours		0		
Oil Changed		Changed		
Sample Status		ABNORMAL		
OIL COND	ITION			
Visc @ 40°C	cSt	50.8		
Acid Number (AN)		1.17		
VOLVO				
Contam	-		<u> </u>	
Water	%	NEG		
Particles >4µm		A 79153		
Particles >6µm		A 7299		
Particles > 14µm		40		
ISO 4406:1999 (c)		23/20/12		
Silicon	ppm	5		
Sodium	ppm	6		
Potassium	ppm	2		
VOLVO				
🤍 WEAR MI	TALS			
Iron	ppm	1 3		
Copper	ppm			
Lead	ppm			
Tin	ppm	<1		
Aluminum	ppm	1		
Chromium	ppm	1		
Molybdenum	ppm	25		
Nickel	ppm	0		
Titanium	ppm	<1		
Silver	ppm	0		
Manganese	ppm	0		
Vanadium	ppm	0		
	5			
Calcium	ppm	1484		
Magnesium	ppm	117		
Zinc	ppm	798		
	ppm	728		
Phosphorus				
	ppm ppm	<1 138		

FAIRCHILD BROTHERS

PO BOX 198 WINFIELD, PA JS 17889 Contact: TOBY STAHL

T: (570)524-9255 F:

Diagnosis

The oil change at the time of sampling has been noted. We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


Depot:FAIWINPAUnique No:10845701Signed:Don BaldridgeReport Date:25 Jan 2024

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: FAIWINPA [WUSCAR] 06069024 (Generated: 01/25/2024 19:09:55) Rev: 1