

CONSTRUCTION EQUIPMENT X48504 VOLVO A25G 752686 - DIESEL ENGINE



Sample No: VCP414619

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No: X48504

| CAMPLE IN | NFORMATION | | | |
|------------------|---------------|----------------|---|----------|
| | W OILI-IM TON | VCD414C10 | _ | <u>.</u> |
| Sample Number | | VCP414619 | | |
| Sample Date | | 07 Feb 2024 | | |
| Machine Hours | | 768 | | |
| Oil Hours | | 0 | | |
| Oil Changed | | N/A | | |
| Sample Status | | ABNORMAL | | |
| VOLVO | | | | |
| OIL CONDI | TION | | | |
| Visc @ 100°C | cSt | 10.7 | | |
| Base Number (BN) | ma KOH/a | ■ 5.1 | | |
| Oxidation (PA) | % | 56 | | |
| | | | | |
| VOLVO | INTION | | | |
| CONTAMIN | IATIUN | | | |
| Water | % | NEG | | |
| Soot % | % | ■0.3 | | |
| Nitration (PA) | % | 80 | | |
| Sulfation (PA) | % | 55 | | |
| Glycol | % | NEG | | |
| Fuel | % | 0.4 | | |
| Silicon | ppm | 68 | | |
| Sodium | ppm | ■ 5 | | |
| Potassium | ppm | 4 | | |
| | | | | |
| WEAR ME | ΤΔΙς | | | |
| _ | | = 42 | _ | |
| Iron | ppm | 43 | | |
| Copper | ppm | <u>▲</u> 342 | | |
| Lead | ppm | 4 | | |
| Tin | ppm | 4 | | |
| Aluminum | ppm | 3 | | |
| Chromium | ppm | ■<1 | | |
| Molybdenum | ppm | 81 | | |
| Nickel | ppm | <u>^</u> 27 | | |
| Titanium | ppm | ■ <1 | | |
| Silver | ppm | 1 | | |
| Manganese | ppm | 7 | | |
| Vanadium | ppm | <1 | | |
| VOLVO | | | | |
| ADDITIVE: | <u> </u> | | | |
| Calcium | ppm | 2320 | | |
| Magnesium | ppm | 12 | | |
| Zinc | ppm | 1176 | | |
| Phosphorus | ppm | 1170 | | |
| Barium | ppm | ■ <1 | | |
| Boron | ppm | 40 | | |
| DOTOTI | PPIII | | | |



SCOTT EQUIPMENT COMPANY LLC - Lake Charles
PO BOX 16955
LAKE CHARLES, LA
US 70616
Contact: TINA LEDOUX
tledoux@scottcompanies.com
T: (337)433-9811

Diagnosis

F: (318)433-6623

No corrective action is recommended at this time. Resample at the next service interval to monitor.The copper level is abnormal. The nickel level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other metal levels are typical for a new component breaking in. Fuel content negligible. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot:VOLVO6244Unique No:10874378Signed:Jonathan HesterReport Date:14 Feb 2024



CONSTRUCTION EQUIPMENT





