CONSTRUCTION EQUIPMENT SW0-069538 LHOIST VOLVO L350H 1007 - FRONT AXLE

 Sample No:
 VCP444440

 Oil Type:
 {unknown}

 Job No:
 SWO-0695381HOIST

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ADDITIVES

16

<1

3049

1275

1131

8

1

90

VOLVO

SAMPLE INFORMATION VCP444440 Sample Number VCP445733 VCP402616 VCP357755 Sample Date 09 Feb 2024 17 Nov 2023 05 Apr 2023 15 Apr 2022 Machine Hours 1802 17555 1551 12518 Oil Hours 0 0 0 0 Oil Changed Not Changd Not Changd Not Changd Changed SEVERE NORMAL Sample Status SEVERE SEVERE **OIL CONDITION** Visc @ 40°C cSt 52.1 52.6 53.7 52.4 CONTAMINATION Water % NEG NEG NEG NEG 24 Silicon 31 23 12 ppm Sodium 0 🔲 2 6 ppm 1 Potassium ppm 2 0 0 0 WEAR METALS 1551 Iron ppm 1161 1047 126 Copper ppm 8 7 **4** 8 Lead ppm 1 < 1 0 < 1 Tin ppm 0 0 0 1 Aluminum 1 <1 2 1 ppm Chromium **4** 2 2 < 1 ppm Molybdenum ppm 2 1 1 4 Nickel 1 0 0 0 ppm Titanium <1 0 0 <1 ppm Silver <1 0 0 <1 ppm

12

2977

1244

1130

7

2

82

0

11

3282

1242

1088

101

8

0

0

2

0

3368

1335

1155

0

116

60

COWIN EQUIPMENT COMPANY

2238 PINSON VALLEY PARKWAY BIRMINGHAM, AL US 35217 Contact: BRANTLY CLAY bclay@cowin.com T: F: (205)856-2106

Diagnosis

We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. The iron level is severe. Gear wear is indicated. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:	VOLVO8528
Unique No:	10883437
Signed:	Don Baldridge
Report Date:	17 Feb 2024

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

