

CONSTRUCTION EQUIPMENT 674384 VOLVO A30G 753001 - WET DISC BRAKE



Sample No: VCP445976
Oil Type: VOLVO WB 102

Job No: 674384

| CAMPLE | INFORMATION | | | | |
|-------------------|-------------|--------------|------------------|----------------|--|
| Sample Number | | VCP445976 | VCP431811 | VCP421057 | |
| Sample Date | | 14 Feb 2024 | 12 Dec 2023 | 18 Jul 2023 | |
| Machine Hours | | 2293 | 1980 | 999 | |
| Oil Hours | | 0 | 0 | 0 | |
| Oil Changed | | Not Changd | Not Changd | Not Changd | |
| | | ABNORMAL | NORMAL | | |
| Sample Status | | ADNUKIVIAL | NORIVIAL | ATTENTION | |
| VOLVO | | | | | |
| OIL CON | DITION | | | | |
| Visc @ 40°C | cSt | ▲ 327 | 45.5 | ▲ 342 | |
| | | | | | |
| VOLVO | AIN A TION | | | | |
| LUNIAN | MINATION | | | | |
| Water | % | NEG | NEG | NEG | |
| Silicon | ppm | 2 | 1 3 | 1 2 | |
| Sodium | ppm | 0 | 4 | ■3 | |
| Potassium | ppm | ■ 0 | 0 | ■3 | |
| | | | | | |
| WEAR N | AETAI C | | | | |
| _ | | | | | |
| Iron | ppm | △ 67 | 1 1 | ■8 | |
| Copper | ppm | 2 | 6 2 | ■25 | |
| Lead | ppm | 0 | _2 | 0 | |
| Tin | ppm | 0 | 0 | ■0 | |
| Aluminum | ppm | ■3 | 0 | - <1 | |
| Chromium | ppm | ■ <1 | 0 | □ 0 | |
| Molybdenum | ppm | 6 | 0 | - <1 | |
| Nickel | ppm | | 0 | ■ 0 | |
| Titanium | ppm | <1 | 0 | 0 | |
| Silver | ppm | 0 | 0 | 0 | |
| Manganese | ppm | ■ <1 | <1 | - <1 | |
| Vanadium | ppm | 0 | 0 | 0 | |
| VOLVO | | | | | |
| ADDITIV | /FS | | | | |
| _ | | ▲ 53 | m 2244 | m 4120 | |
| Calcium | ppm | | 3344 | 4120 | |
| Magnesium Zinc | ppm | | □ 14 □ 1404 | □ 19 □ 1656 | |
| | ppm | ▲ 15 | ■ 1404 ■ 1301 | □ 1656 | |
| Phosphorus | ppm | 961 | 1301 | □ 1369 | |
| Barium | ppm | 0 | 0 | <1 = 126 | |
| Boron | ppm | 177 | 1 116 | ■ 126 | |



BLUE GOOSE GROWERS

16059 W ORANGE AVE FT PIERCE, FL US 34945

Contact: SERVICE MANAGER

T: (772)461-3020 F:

Diagnosis

No corrective action is recommended at this time. We recommend an early resample to monitor this condition. The iron level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. Additive levels indicate the addition of a different brand, or type of oil. Confirm oil type.

Depot:BLUFORUnique No:10886161Signed:Don BaldridgeReport Date:21 Feb 2024



CONSTRUCTION EQUIPMENT





