

## CONSTRUCTION EQUIPMENT RYAN GOLF VOLVO A40G 752117 - DIESEL ENGINE



Sample No: VCP435617

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No: RYAN GOLF

VOLVO				
SAMPLE IN	NFORMATION			
Sample Number		VCP435617	 	
Sample Date		19 Feb 2024	 	
Machine Hours		572	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
OIL CONDI.	TION			
Visc @ 100°C	cSt	<b>10.9</b>	 	
Base Number (BN)		■ 5.5	 	
Oxidation (PA)	%	60	 	
Oxidation (FA)	70	00		
VOLVO				
CONTAMIN	NATION			
Water	%	NEG	 	
Soot %	%	■ 0.3	 	
Nitration (PA)	%	84	 	
Sulfation (PA)	%	55	 	
Glycol	%	NEG	 	
Fuel	%	■ 0.3	 	
Silicon	ppm	<b>■30</b>	 	
Sodium	ppm	<b>3</b>	 	
Potassium	ppm	<b>4</b>	 	
WEAR ME	TALS			
Iron	ppm	<b>23</b>	 	
Copper	ppm	<u>△</u> 298	 	
Lead	ppm	<b>1</b>	 	
Tin	ppm	<u> </u>	 	
Aluminum	ppm	<u> </u>	 	
Chromium	ppm	<u> </u>	 	
Molybdenum	ppm	■83	 	
Nickel	ppm	<u> </u>	 	
Titanium	ppm	<b>   &lt;1</b>	 	
Silver	ppm	O	 	
Manganese	ppm	<b>2</b>	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	<b>1990</b>	 	
Magnesium	ppm	<b>20</b>	 	
Zinc	ppm	<b>1114</b>	 	
Phosphorus	ppm	<b>■</b> 942	 	
Barium	ppm	<b>2</b>	 	
Boron	ppm	■30	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other metal levels are typical for a new component breaking in. Fuel content negligible. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot:VOLVO0093Unique No:10900464Signed:Jonathan HesterReport Date:04 Mar 2024



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

