


## **CONSTRUCTION EQUIPMENT**

TAKEUCHI TB2 150 5 1460 1000 - HYDRAULIC SYSTEM

Sample No: VCP418203

Oil Type: FIRE-RESISTANT FLUID ISO 46

Job No: UF



CONTAMINATION							
Water	%	NEG					
Particles >4µı	m	<b>22923</b>					
Particles >6µm		<b>4</b> 3426					
Particles > 14	μm	<b>110</b>					
ISO 4406:1999 (c)		22/19/14					
Silicon	ppm	<b>■&lt;1</b>					
Sodium	ppm	<b>■&lt;1</b>					
Potassium	ppm	<b>1</b>					

WEAR N	METALS			
Iron	ppm	<b>1</b>	 	
Copper	ppm	<b>-&lt;1</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	■0	 	
Aluminum	ppm	<b>-&lt;1</b>	 	
Chromium	ppm	<b>■</b> 0	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>    &lt; 1</b>	 	
Vanadium	ppm	0	 	

ADDITIVES							
Calcium	ppm	<b>■9</b>					
Magnesium	ppm	■3					
Zinc	ppm	<b>52</b>					
Phosphorus	ppm	<b>■258</b>					
Barium	ppm	<b>■</b> 0					
Boron	ppm	<b>■</b> 0					



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
9601 BOGGY CREEK RD
ORLANDO, FL
US 32824
Contact: Robert LaPlante
robert.laplante@altg.com
T: (407)508-9736
F: (407)659-8720

## Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0096Unique No:10901129Signed:Don BaldridgeReport Date:01 Mar 2024



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

