

# **CONSTRUCTION EQUIPMENT**LIEBHERR L524 020079-659 - DIESEL ENGINE



**Sample No:** VCP06152513

Oil Type: VALVOLINE ALLFLEET 15W40

Job No:

VOLVO					
SAMPLE IN	NFORMATION				
Sample Number	-	VCP06152513	VCP306499	LHMC131184	LHMC109987
Sample Date		02 Apr 2024	17 Feb 2021	18 Mar 2019	08 Sep 2016
Machine Hours		0	0	11557	9417
Oil Hours		0	0	500	0
Oil Changed		N/A	Changed	Changed	Changed
Sample Status		SEVERE	NORMAL	NORMAL	NORMAL
OIT CONDI.	TION				
Visc @ 100°C	cSt	118	<b>□</b> 15.1	□ 14.39	<b>14.00</b>
		<b>110</b>	13.1	14.33	14.00
Base Number (BN)	mg KOH/g %		70	 F7	
Oxidation (PA)	%	99	78	57	<b>■</b> 36
VOLVO					
CONTAMIN	IATION				
Water	%	NEG	NEG	NEG	NEG
Soot %	%	■1.8	■1.4	■ 0.9	■0.1
Nitration (PA)	%	238	95	109	■33
Sulfation (PA)	%	2	66	53	■30
Glycol	%	<b>▲</b> 0.12	NEG	NEG	NEG
uel	%	<1.0	<1.0	<1.0	<1.0
Silicon	ppm	<b>41</b>	<b>4</b>	<b>5</b>	<b>2</b>
Sodium	ppm	<b>△</b> 3125	<b>-</b> <1	<b>4</b>	<b>4</b>
Potassium	ppm	<b>144</b>	<b>2</b>	<b>0</b>	< 1
WEAR ME	ΤΔΙς				
_					
ron	ppm	▲ 162	<b>□</b> 55	■36	<b>9</b>
Copper	ppm	<u>^</u> 95	<b>2</b>	<b>=</b> <1	<b>=</b> <1
_ead 	ppm	<b>▲</b> 105	8	1	<b>-</b> <1
Γin • ·	ppm	<u>^</u> 9	<1	1	<b>=</b> <1
Aluminum	ppm	<b>10</b>	<1	<b>3</b>	1
Chromium	ppm	<b>5</b>	1	1	<b>=</b> <1
Molybdenum	ppm	<b>345</b>	■33	<b>=</b> <1	5
Nickel	ppm	<b>5</b>	1	<b>-</b> <1	<1
Гitanium	ppm	<1	0	<1	0
Silver	ppm	<b>■ &lt;1</b>	0	0	0
Manganese	ppm	<b>4</b>	<1	<b>1</b> < 1	<1
/anadium	ppm	<1	0	0	0
VOLVO					
ADDITIVE!	5				
Calcium	ppm	<b>948</b>	<b>1811</b>	■3922	1234
Magnesium	ppm	<b>□</b> 542	<b>664</b>	<b>260</b>	778
Zinc	ppm	882	□ 1346	1289	■1165
Phosphorus	ppm	<b>762</b>	1214	1084	1053
Barium	ppm	<b>2</b>	0	0	<b>0</b>
Boron	ppm	<b>282</b>	<b>4</b> 4	□ 184	24
	1-1				



#### SIMS METAL MANAGEMENT

2500 S. PAULINA CHICAGO, IL US 60608 Contact: RYAN WISE ryan.wise@simsmm.com T:

F:

### Diagnosis

We advise that you check for the source of the coolant leak. Check for low coolant level. We recommend that you drain the oil and perform a filter service on this component if not already done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.Cylinder, crank, or cam shaft wear is indicated. Bearing and/or bushing wear is indicated. Sodium and/or potassium levels are high. There is a high concentration of glycol present in the oil. The oil viscosity is higher than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot:SIMCHIILUnique No:10982591Signed:Jonathan HesterReport Date:23 Apr 2024

Contact/Location: RYAN WISE - SIMCHIIL



## **CONSTRUCTION EQUIPMENT**





