

CONSTRUCTION EQUIPMENT VOLVO SD115B 236554 - HYDRAULIC SYSTEM



Sample No: VCP437845

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

Job No:

Boron

| VOLVO | | | | | |
|--------------------|-----------------|---------------|----------------|-------------|---------------|
| | INFORMATION | | | | |
| Sample Number | - | VCP437845 | VCP386096 | VCP345510 | VCP322125 |
| Sample Date | | 13 Feb 2024 | 13 Sep 2022 | 01 Feb 2022 | 17 Jun 2021 |
| Machine Hours | | 5960 | 4714 | 4168 | 3705 |
| Oil Hours | | 0 | 500 | 2000 | 0 |
| Oil Changed | | Not Changd | Not Changd | Changed | N/A |
| Sample Status | | ABNORMAL | ABNORMAL | ATTENTION | MARGINAL |
| OIL CONE | DITION | | | | |
| Visc @ 40°C | cSt | 63.7 | 58.6 | 67.9 | □ 52.6 |
| Acid Number (AN | | ■0.56 | 0.43 | □ 0.36 | 0.413 |
| Acid Ivaliber (Air | i) ilig kori, g | 0.30 | 0.43 | 0.50 | 0.415 |
| VOLVO | UNIA TION | | | | |
| LUNTAM | INATION | | | | |
| Water | % | NEG | NEG | NEG | NEG |
| Particles >4µm | | | <u>▲</u> 98729 | 4702 | ■5997 |
| Particles >6µm | | | 5047 | 277 | ■1022 |
| Particles >14µm | | | 100 | 2 4 | ■89 |
| ISO 4406:1999 (c) | | | 24/20/14 | 19/15/12 | 20/17/14 |
| Silicon | ppm | ■<1 | - <1 | - <1 | < 1 |
| Sodium | ppm | 2 | 0 | 0 | < 1 |
| Potassium | ppm | ■<1 | 0 | 1 | 0 |
| | | | | | |
| WEAR M | ETALS | | | | |
| Iron | ppm | 10 | 1 3 | ■8 | <u></u> 32 |
| Copper | ppm | 7 | 6 | 1 0 | 1 9 |
| Lead | ppm | ■0 | < 1 | 1 | ■3 |
| Tin | ppm | ■0 | 0 | 0 | <1 |
| Aluminum | ppm | ■0 | - <1 | - <1 | - <1 |
| Chromium | ppm | ■0 | 0 | 0 | - <1 |
| Molybdenum | ppm | 1 | - <1 | - <1 | - <1 |
| Nickel | ppm | ■0 | 0 | □ 0 | 0 |
| Titanium | ppm | 0 | 0 | 0 | 0 |
| Silver | ppm | 0 | 0 | 0 | 0 |
| Manganese | ppm | 0 | - <1 | <u> </u> | - <1 |
| Vanadium | ppm | 0 | 0 | 0 | 0 |
| VOLVO | | | | | |
| ADDITIV | ES | | | | |
| Calcium | ppm | 69 | ■139 | ■90 | 6 3 |
| Magnesium | ppm | ■8 | 4 | 4 | 4 |
| Zinc | ppm | 449 | ■382 | 451 | 410 |
| Phosphorus | ppm | ■ 357 | ■367 | ■348 | ■343 |
| Barium | ppm | ■0 | 0 | □0 | ■0 |
| _ | | | | | |



RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com T:

Diagnosis

F:

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. Viscosity of sample indicates oil is within ISO 68 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.

Depot:RIPTAMUnique No:10995719Signed:Don BaldridgeReport Date:26 Apr 2024



CONSTRUCTION EQUIPMENT





GRAPHS







