

CONSTRUCTION EQUIPMENT SWA499940 VOLVO L220H 2541 - REAR AXLE



Sample No: VCP419945 Oil Type: VOLVO WB 102 Job No: SWA499940

TAMPI	E INFORMATION				
Sample Number		VCP419945	VCP438865	VCP251529	
Sample Date		18 Apr 2024	16 Apr 2024	15 Aug 2019	
Machine Hours		12417	12474	4400	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Changed	
Sample Status		ABNORMAL	NORMAL	ABNORMAL	
VOLVO					
OIL CON	IDITION				
Visc @ 40°C	cSt	44.5	□ 73.3	74.6	
Visc & 10 C	CSC			7 1.0	
VOLVO					
CONTAI	MINATION				
Water	%	△ 0.941	NEG	△ 0.221	
Silicon	ppm	■23	1 2	7	
Sodium	ppm	■<1	1	2	
Potassium	ppm	■0	0	2	
WEAR	METALS				
_		= 22	 24	= 20	
Iron	ppm	■33	2 4	■38	
Copper	ppm	0	0	7	
Lead 	ppm	0	0	1	
Tin	ppm	■ <1	0	0	
Aluminum	ppm	2	- <1	 <1	
Chromium	ppm	0	- <1	 <1	
Molybdenum	ppm	0	3	5	
Nickel	ppm	■0	0	 <1	
Titanium	ppm	<1	0	0	
Silver	ppm	0	0	0	
Manganese	ppm		1	3	
Vanadium	ppm	0	0	0	
VOLVO					
ADDITIV	VES				
Calcium	ppm	□ 3237	■ 3727	3148	
Magnesium	ppm	16	1 6	25	
Zinc	ppm	■ 1445	□ 1425	1238	
Phosphorus	ppm	1268	1216	914	
Hospitolus	PPIII	1200	1210	J 1 →	

0 84 0

39



PREFERRED MATERIALS

4636 SCARBOROUGH DR LUTZ, FL US 33559 Contact: Service Manager

T: (850)479-3004

F:

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. Appearance is hazy. There is a high concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot: **PRELUT Unique No:** 10996160 Signed: Don Baldridge Report Date: 29 Apr 2024

0

23

ppm

ppm

Barium

Boron



CONSTRUCTION EQUIPMENT





