



CONSTRUCTION EQUIPMENT

381461 VOLVO G940 41225 - TRANSMISSION (AUTO)



Sample No: VCP353348
Oil Type: VOLVO AT 102
Job No: 381461



INFORMATION SUR L' CHANTILLON

Numéro d'échant.	VCP353348	---	---	---
Date d'échant.	11 Oct 2023	---	---	---
Heures de la Machine	12371	---	---	---
Heures de l'huile	0	---	---	---
Huile changée	Not Changed	---	---	---
Statut de l'échant.	ABNORMAL	---	---	---

VILLE DE ST-RAYMOND

375 RUE ST-JOSEPH
 ST RAYMOND, QC
 CA G3L 1A1
 Contact:

T:
 F: (418)337-2203



ÉTAT D'HUILE

Visc 40°C	cSt	■ 30.7	---	---	---
-----------	-----	--------	-----	-----	-----



CONTAMINATION

Eau	%	▲ 0.772	---	---	---
Silicium	ppm	■ 6	---	---	---
Sodium	ppm	■ 14	---	---	---
Potassium	ppm	■ 11	---	---	---



M TAUX D'USURE

Fer	ppm	■ 58	---	---	---
Cuivre	ppm	■ 3	---	---	---
Plomb	ppm	■ 8	---	---	---
Étain	ppm	■ 0	---	---	---
Aluminium	ppm	■ 3	---	---	---
Chrome	ppm	■ <1	---	---	---
Molybdène	ppm	■ 2	---	---	---
Nickel	ppm	■ <1	---	---	---
Titane	ppm	0	---	---	---
Argent	ppm	■ <1	---	---	---
Manganèse	ppm	■ 1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIFS

Calcium	ppm	■ 159	---	---	---
Magnésium	ppm	■ 15	---	---	---
Zinc	ppm	143	---	---	---
Phosphore	ppm	■ 272	---	---	---
Baryum	ppm	■ <1	---	---	---
Bore	ppm	■ 83	---	---	---

Diagnostic

We advise that you check for the source of water entry. We recommend that you drain the fluid from the component if this has not already been done. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate concentration of water present in the fluid. Test for glycol is negative. The fluid is no longer serviceable due to the presence of contaminants.

Depot: VILSTR
Unique No: 5658749
Signed: Kevin Marson
Report Date: 18 Oct 2023



CONSTRUCTION EQUIPMENT



GRAPHS

