



R5-7417 6610421065 - TRANSMISSION (AUTO)

Sample No: VPA055963
Oil Type: NOT GIVEN

SAMPLE INFORM	ATION			
Sample Number		VPA055963	 	
Sample Date		15 Aug 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
		7121101111111		
OIL CONDITION				
Visc @ 40°C	cSt	37.4	 	
CONTAMINATION				
Silicon	ppm	<u>^</u> 26	 	
Sodium	ppm	<b>■</b> 57	 	
Potassium	ppm	<u></u> 5	 	
WEAR METALS				
PQ		<b>4</b>	 	
Iron	ppm	<u> </u>	 	
Copper	ppm	<b>114</b>	 	
Lead	ppm	<b>29</b>	 	
Tin	ppm	<b>4</b>	 	
Aluminum	ppm	<b>■</b> 57	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	4	 	
Nickel	ppm	<b>1</b>	 	
Titanium	ppm	<b>0</b>	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	4	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	35	 	
Magnesium	ppm	15	 	
Zinc	ppm	103	 	
Phosphorus	ppm	243	 	
Barium	ppm	0	 	
Boron	ppm	23	 	

## **ABC TRANSMISSIONS LTD**

9357 193 St SURREY, BC CA V4N 4E7 Contact: Service Manager service@abctransmission.com T: (604)882-2886 F:

## Diagnosis

We advise that you check all areas where dirt can enter the system. We recommend that you drain the fluid from the component if this has not already been done. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.Iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. There is a moderate concentration of dirt present in the fluid. High amount of ingressed dirt has caused abrasive wear to the component. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:ABC935SURUnique No:5630828Signed:Kevin MarsonReport Date:23 Aug 2023

## **OIL ANALYSIS REPORT**



