



SVENDSENS BAY MARINE JOHN DEERE RG6135L040310 - PORT DIESEL ENGINE

Sample No: VPA047534

Oil Type: JOHN DEERE ENGINE OIL PLUS 50 II 15W40

Report Id: VP601779 [WUSCAR] 06023442 (Generated: 12/07/2023 17:14:43) Rev: 1

SAMPLE INFORMAT	TION			
Sample Number		VPA047534	VPA047594	
Sample Date		30 Nov 2023	07 Jun 2023	
Machine Hours		1527	414	
Oil Hours		0	194	
Oil Changed		N/A	Not Changd	
Sample Status		SEVERE	ABNORMAL	
		0212.12	71311011111111	
OIL CONDITION				
Visc @ 100°C	cSt	<u> </u>	<u></u> 11.4	
Base Number (BN)	mg KOH/g	7.2	9.4	
Oxidation (PA)	%	51	55	
CONTAMINATION				
CONTAMINATION				
Water	%	NEG	NEG	
Soot %	%	■0.3	0.1	
Nitration (PA)	%	55	48	
Sulfation (PA)	%	51	54	
Glycol	%	NEG	NEG	
Fuel	%	18.1	△ 5.9	
Silicon	ppm	7	9	
Sodium	ppm	2	0	
Potassium	ppm	■ 0	2	
WEAR METALS				
Iron	ppm	■8	4	
Copper	ppm	<u>^</u> 26	1 4	
Lead	ppm	2	<u></u> 4	
Tin	ppm	<u></u> 2	2	
Aluminum	ppm	2	0	
Chromium	ppm	■0	0	
Molybdenum	ppm	■204	■233	
Nickel	ppm	■0	- <1	
Titanium	ppm	0	0	
Silver	ppm	■ 0	0	
Manganese	ppm	0	<u></u> <1	
Vanadium	ppm	0	0	
ADDITIVES				
Calcium	ppm	1247	□ 1270	
Magnesium	ppm	665	738	
Zinc	ppm	■ 987	□ 952	
Phosphorus	ppm	810	803	
Barium	ppm	■0	■0	
Boron	ppm	■ 186	273	
DOIOII	phili	■ 100	<u> </u>	

Bay Marine Boatworks Inc.

310 West Cutting Blvd. RICHMOND, CA US 94804

Contact: Jaime Figueroa ifiqueroa@baymarineboatworks.com

T: F:

Diagnosis

We advise that you check the fuel injection system. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition. The copper level is marginal. All other component wear rates are normal. There is a high amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

Depot: VP601779 **Unique No:** 10767942 Signed: Doug Bogart Report Date: 07 Dec 2023

OIL ANALYSIS REPORT



