

Report Id: VP531377 [WUSCAR] 06024985 (Generated: 12/06/2023 15:55:42) Rev: 1



NORTHLIGHT/3299 FISCHER PANDA 2100212 - CENTER GENSET

Sample No: VPA049675
Oil Type: SHELL 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA049675		
Sample Date		29 Nov 2023		
Machine Hours		114		
Oil Hours		0		
Oil Changed		Changed		
Sample Status		NORMAL		
		HORWAL	_	
OIL CONDITION				
Visc @ 100°C	cSt	13.3		
Base Number (BN)	mg KOH/g	8.6		
Oxidation (PA)	%	63		
CONTAMINATION				
Water	%	NEG		
Soot %	%	NEG ■ 0.1		
Nitration (PA)	%	48		
Sulfation (PA)	%	54		
Glycol	%	NEG		
Fuel	%	<1.0		
Silicon	ppm	■ 4		
Sodium	ppm	0		
Potassium	ppm	■8		
WEAD METALS		_		
WEAR METALS				
Iron	ppm	■8		
Copper	ppm	1		
Lead	ppm	■0		
Tin	ppm	■ 0		
Aluminum	ppm	1		
Chromium	ppm	■ <1		
Molybdenum	ppm	10		
Nickel	ppm	■ 0		
Titanium	ppm	<1		
Silver	ppm	■0		
Manganese	ppm	0		
Vanadium	ppm	0		
ADDITIVES				
Calcium	ppm	2435		
Magnesium	ppm	■39		
Zinc	ppm	1153		
Phosphorus	ppm	1044		
Barium	ppm	■ 0		
Boron	ppm	204		

GRAND BANKS

450 SW SALEM RD STUART, FL US 34994 Contact: ROBERT ANTONA roberta@gbmarinegroup.com T: (609)384-5290 F:

Diagnosis

Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP531377Unique No:10769485Signed:Sean FeltonReport Date:06 Dec 2023





