



NOT GIVEN VPA06193701 (S/N NO SIF/NO INFO ON BOTTLE) - GENSET

Sample No: VPA06193701
Oil Type: {unknown}

SAMPLE INFORMAT	TION			
		VPA06193701	 	
Sample Number Sample Date		20 May 2024	 	
Machine Hours		0 Way 2024	 	
Oil Hours		0	 	
Oil Changed		N/A SEVERE	 	
Sample Status		SEVERE	 	
OIL CONDITION				
Visc @ 100°C	cSt	<u> </u>	 	
Base Number (BN)	mg KOH/g	8.5	 	
Oxidation (PA)	%	69	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	NEG ■ 0.1	 	
Nitration (PA)	%	48	 	
Sulfation (PA)	%	56	 	
	%	NEG	 	
Glycol Fuel	%	NEG ▲ 8.2		
Silicon		▲ 75	 	
Sodium	ppm			
Potassium	ppm	8	 	
Potassium	ppm	6	 	
WEAR METALS				
Iron	ppm	5	 	
Copper	ppm	■ 3	 	
Lead	ppm	2	 	
Tin	ppm	■<1	 	
Aluminum	ppm	2	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	12	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	<1	 	
Silver	ppm	■ 0	 	
Manganese	ppm	3	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	1605	 	
Magnesium	ppm	223	 	
Zinc	ppm	962	 	
Phosphorus	ppm	865	 	
Barium	ppm	0	 	
Boron	ppm	162	 	
50.011	Phili	.02		

Power Products Systems LLC

90 Bay State Road WAKEFIELD, MA US 01880 Contact: ERIC JELLISON ejellison@nedda.com T: (781)831-8924 F:

Diagnosis

We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a high amount of fuel present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot:VP153550Unique No:11050453Signed:Jonathan HesterReport Date:31 May 2024





