

PROBLEM SUMMARY


[177710] WES GG LUBE SYSTEM

Lube System

EASTMAN TURBO OIL 2380 (200 LTR)

Sample Rating Trend

COMPONENT CONDITION SUMMARY



RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS									
Sample Status			SEVERE	NORMAL	NORMAL				
Particles >4µm	ASTM D7647	>5000	61142	1699	11863				
Particles >6µm	ASTM D7647	>1300	A 8951	98	954				
Oil Cleanliness	ISO 4406 (c)	>19/17/14	23/20/15	18/14/11	21/17/12				

Customer Id: NEWSTJ Sample No.: WC838122 Lab Number: 02365701 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS								
Action	Status	Date	Done By	Description				
Change Filter	MISSED	Jan 21 2022	?	We recommend you service the filters on this component.				
Resample	MISSED	Jan 21 2022	?	Resample in 30-45 days to monitor this situation.				
Check Breathers	MISSED	Jan 21 2022	?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.				
Check Seals	MISSED	Jan 21 2022	?	Check seals and/or filters for points of contaminant entry.				

HISTORICAL DIAGNOSIS

29 Sep 2016 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



26 Aug 2013 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



30 Apr 2013 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The TAN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Area [177710] **WES GG LUBE SYSTEM**

Lube System

EASTMAN TURBO OIL 2380 (200 LTR)

Sample Rating Trend



DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

Particles >4µm are severely high. Particles >6µm are abnormally high. Particles >14µm are notably high.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC838122	WC933721	WC838205
Sample Date		Client Info		18 Jun 2020	29 Sep 2016	26 Aug 2013
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	NORMAL	NORMAL
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	<1	<1	<1
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	0	0	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>20	<1	<1	<1
Lead	ppm	ASTM D5185(m)	>20	0	<1	<1
Copper	ppm	ASTM D5185(m)	>20	<1	<1	1
Tin	ppm	ASTM D5185(m)	>20	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1	0	<1
Barium	ppm	ASTM D5185(m)	0	0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)	0	<1	0	<1
Calcium	ppm	ASTM D5185(m)	0	0	0	0
Phosphorus	ppm	ASTM D5185(m)	2500	2751	2694	2844
	ppm	(/	0	<1	<1	2
Sulfur	ppm	ASTM D5185(m)	0	7	10	9
Lithium	ppm	ASTM D5185(m)		<1	<1	0
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	4	3	3
Sodium	ppm	ASTM D5185(m)		<1	0	<1
Potassium	ppm	ASTM D5185(m)	>20	1	<1	0
FLUID CLEANLINE	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	61142	1699	11863
Particles >6µm		ASTM D7647	>1300	<u>A</u> 8951	98	954
Particles >14μm		ASTM D7647	>160	227	15	38
Particles >21µm		ASTM D7647	>40	53	5	7
Particles >38µm		ASTM D7647	>10	1	0	0
r artiolog > oopin						-

ASTM D7647 >3

ISO 4406 (c) >19/17/14 **23/20/15**

Particles >71μm


Oil Cleanliness

18/14/11

21/17/12



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number Unique Number

: WC838122 : 02365701 : 5073145

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Recieved : 20 Jul 2020 Diagnosed : 20 Jul 2020

: Wes Davis Diagnostician Test Package : IND 2 (Additional Tests: TAN Man)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

NEWFOUNDLAND POWER INC.

50 DUFFY PLACE, PO BOX 8910 ST. JOHNS, NL CA A1B 3P6

Contact: Paul Martin pmartin@newfoundlandpower.com

Contact/Location: Paul Martin - NEWSTJ

F: (709)737-2926

T: