


PROBLEM SUMMARY


[188538] Machine Id CAB G THBR


Component **Bearing**

MOBIL DTE OIL HVY MEDIUM (--- GAL)









RECOMMENDATION

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. We advise that you check all areas where dirt can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this oil. We recommend that you change the oil. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS										
Sample Status				SEVERE	NORMAL	NORMAL				
Phosphorus	ppm	ASTM D5185(m)		<u></u> <1	2	230				
Silicon	ppm	ASTM D5185(m)	>12	5 1	2	<1				
Precipitate	scalar	Visual*	NONE	▲ LIGHT	NONE	NONE				
Free Water	scalar	Visual*		1 %	NEG	NEG				

Customer Id: NEWSTJ Sample No.: WC0445218 Lab Number: 02467372 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	We recommend that you change the oil.		
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.		
Resample			?	We recommend an early resample to monitor this condition.		
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.		
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.		
Check Dirt Access			?	We advise that you check all areas where dirt can enter the system.		
Check Fluid Source			?	Confirm the source of the lubricant being utilized for top-up/fill.		
Check Water Access			?	We advise that you check for the source of water entry.		
Check Seals			?	Check seals and/or filters for points of contaminant entry.		
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.		

HISTORICAL DIAGNOSIS

26 Feb 2007 Diag:

NORMAL



Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is no indication of any contamination in the component. The condition of oil is suitable for further service.



02 Jun 2006 Diag:

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The condition of oil is suitable for further service.



27 Feb 2006 Diag:

DEGRADATION



We recommend an early resample to monitor this condition.All component wear rates are normal. There is no indication of any contamination in the component. The TAN level is at the top-end of the recommended limit. The condition of oil is suitable for further service.






OIL ANALYSIS REPORT

[188538] **CAB G THBR**

Bearing

MOBIL DTE OIL HVY MEDIUM (--- GAL)



DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. We advise that you check all areas where dirt can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this oil. We recommend that you change the oil. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

Free water present. Elemental level of silicon (Si) above normal indicating ingress of seal material.


Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The white residue present in the sample is oil additive precipitate. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

		Feb 200	6 Jun2006	Feb2007 F	lov2021	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0445218	PC293389	PC293063
Sample Date		Client Info		26 Nov 2021	26 Feb 2007	02 Jun 2006
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	NORMAL	NORMAL
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0		
Iron	ppm	ASTM D5185(m)	>63	9	<1	9
Chromium	ppm	ASTM D5185(m)		0	0	0
Nickel	ppm	ASTM D5185(m)		<1	0	<1
Titanium	ppm	ASTM D5185(m)		0	<1	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>2	0	0	0
Lead	ppm	ASTM D5185(m)	>161	3	<1	2
Copper	ppm	ASTM D5185(m)	>13	<1	<1	4
Tin	ppm	ASTM D5185(m)	>27	<1	<1	4
Antimony	ppm	ASTM D5185(m)		<1		
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1	0	0
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	<1
Magnesium	ppm	ASTM D5185(m)		0	0	0
Calcium	ppm	ASTM D5185(m)		<1	<1	<1
Phosphorus	ppm	ASTM D5185(m)		<u></u> <1	2	230
Zinc	ppm	ASTM D5185(m)		8	2	6
Sulfur	ppm	ASTM D5185(m)		2053	1636	712
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	5	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>12	5 1	2	<1
Sodium	ppm	ASTM D5185(m)		0	<1	4
Potassium	ppm	ASTM D5185(m)	>20	<1	<1	<1
FLUID DEGRADA	NOITA	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		0.06	0.03	2.73



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Sample No. Lab Number **Unique Number**

: WC0445218

: 5344290

Received : 02467372

Diagnosed : 26 Jan 2022 Diagnostician : Kevin Marson

Test Package : IND 2 (Additional Tests: Bottom, TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

50 DUFFY PLACE, PO BOX 8910 ST. JOHNS, NL CA A1B 3P6

Contact: Shane Reid sreid@newfoundlandpower.com

T: (709)737-5209 F: (709)737-2926