

PROBLEM SUMMARY

Area Banbury 1 Machine Id BB01 Racine Component

Hydraulic System Fluid SHELL TELLUS S3 M 68 (80 GAL)

COMPONENT CONDITION SUMMARY



Sample Rating Trend ISO



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS Sample Status

Sample Status				SE	VERE	SEVERE	SEVERE
Particles >4µm		ASTM D7647	>5000		152254	165407	1 89138
Particles >6µm		ASTM D7647	>1300		82408	125335	121428
Particles >14µm		ASTM D7647	>160		2494	12307	b 5341
Particles >21µm		ASTM D7647	>40		233	776	<u> </u>
Oil Cleanliness		ISO 4406 (c)	>19/17/14		24/24/18	25/24/21	25/24/20
White Metal	scalar	Visual*	NONE	\	VLITE	NONE	NONE
PrtFilter						no image	no image

Customer Id: GOONAP Sample No.: WC0754391 Lab Number: 02537558 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 <u>Kevin.Marson@wearcheck.com</u>

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECONNINENDED A	CHONS			
Action	Status	Date	Done By	Description
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.
Resample			?	Resample in 30-45 days to monitor this situation.
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.
Check Fluid Source			?	Confirm the source of the lubricant being utilized for top-up/fill.
Check For Visual Metal			?	We advise that you check for visible metal particles in the oil.
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.

HISTORICAL DIAGNOSIS



IS0

27 Oct 2022 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. Particles >14µm are severely high. Particles >21µm are severely high. Particles >6µm are severely high. Oil Cleanliness are severely high. Particles >4µm are severely high. Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



view report

05 Nov 2021 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. Particles >14µm are severely high. Particles >6µm are severely high. Particles >4µm are severely high. Particles >21µm are abnormally high. Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



22 Sep 2021 Diag: Kevin Marson We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We recommend that you drain the oil from the component if this has not already been done. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Iron ppm levels are noted. Light concentration of visible metal present. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. Particles >14µm are severely high. Particles >21µm are severely high. Particles >6µm are severely high. Particles >4µm are severely high. Lithium (Li) level abnormal, indicates possible grease contamination. Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.





OIL ANALYSIS REPORT

Sample Rating Trend

Banbury 1 **BB01** Racine

Component **Hydraulic System** SHELL TELLUS S3 M 68 (80 GAL)

DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

A Wear

Light concentration of visible metal present.

Contamination

Particles >14µm are severely high. Particles >6µm are severely high. Oil Cleanliness are severely high. Particles >4µm are severely high. Particles >21µm are abnormally high.

Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.



Report Id: GOONAP [WCAMIS] 02537558 (Generated: 08/08/2023 14:32:52) Rev: 1



SAMPLE INFORM		method	limit/base	current	nistory i	nistory2
Sample Number		Client Info		WC0754391	WC0664080	WC0636014
Sample Date		Client Info		05 Feb 2023	27 Oct 2022	05 Nov 2021
Machine Age		Client Info		0	0	0
Oil Age		Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
		ام مالح میں	1:00:14/16-0-0-0		Intertowned	biotom O
WEAR METALS		method	limit/base	current	nistory i	nistory∠
Iron	ppm	ASTM D5185(m)	>20	2	5	3
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	0	0	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>20	0	<1	<1
Lead	ppm	ASTM D5185(m)	>20	1	2	1
Copper	ppm	ASTM D5185(m)	>20	<1	2	1
Tin	ppm	ASTM D5185(m)	>20	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1	0	<1
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)		3	11	10
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		<1	0	<1
Calcium	ppm	ASTM D5185(m)		52	45	44
Phosphorus	ppm	ASTM D5185(m)		60	60	60
Zinc	ppm	ASTM D5185(m)	0	8	13	7
Sulfur	ppm	ASTM D5185(m)		214	252	192
Lithium	ppm	ASTM D5185(m)		1	2	2
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	<1	1	<1
Sodium	ppm	ASTM D5185(m)		2	0	<1
Potassium	ppm	ASTM D5185(m)	>20	<1	0	<1
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	152254	165407	• 189138
Particles >6µm		ASTM D7647	>1300	e 82408	125335	121428
Particles >14µm		ASTM D7647	>160	2494	12307	b 5341
Particles >21µm		ASTM D7647	>40	<u> </u>	776	A 221
Particles >38µm		ASTM D7647	>10	4	13	5
Particles >71µm		ASTM D7647	>3	0	2	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	2 4/24/18	25/24/21	• 25/24/20
FLUID DEGRADA	TION	method	limi <u>t/base</u>	current	history1	history2
Acid Number (AN)	mg KOH/a	ASTM D974*		0.10	0.10	0.15
(/	J .=					

Submitted By: ?



Î

number of particles (per 1

OIL ANALYSIS REPORT





no image

VLITE

NONE

NONE

NONE

NONE

VLITE

NORML

NORML

NEG

NEG

65.5

NONE

NONE

NONE

NONE

VLITE

NONE

NORML

NORML

NEG

NEG

65.1

NONE

NONE

NONE

NONE

LIGHT

NONE

NORML

NORML

history

no image

NEG

NEG

67.8



Goodyear Napanee 388 GOODYEAR ROAD NAPANEE, ON CA K7R 3L2 Contact: Steve Cote steve.cote@goodyear.com T: (613)354-7739 F: (613)354-7798

Report Id: GOONAP [WCAMIS] 02537558 (Generated: 08/08/2023 14:32:53) Rev: 1

I/LLONEV

ISO 17025:2017 Accredited

Laboratory

CALA

Laboratory

Sample No.

Lab Number

Unique Number

: WC0754391

: 02537558

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

: 5526558

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

Diagnostician : Kevin Marson

: 06 Feb 2023

: 07 Feb 2023

Received

Test Package : IND 2 (Additional Tests: Bottom, BottomAnalysis, FilterPatch)

Diagnosed

-ah13/1

Submitted By: ?