



Area MANITOU FALLS GS Machine Id FP2G2


Component **Turbine Bearing** Fluid ESSO TERESSO ISO 46 (--- GAL)

COMPONENT CONDITION SUMMARY









WEAR

RECOMMENDATION

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this oil. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend that you change the oil. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS

PROBLEMATIC I	TEST RESULTS					
Sample Status				SEVERE	ABNORMAL	ABNORMAL
Iron	ppm	ASTM D5185(m)	>20	ම 79	6	5
Tin	ppm	ASTM D5185(m)	>20	🔺 15	<1	<1
Particles >4µm		ASTM D7647	>10000	e 2004347	▲ 70270	▲ 57082
Particles >6µm		ASTM D7647	>2500	🛑 1363311	4 704	<u> </u>
Particles >14µm		ASTM D7647	>160	e 214397	9	152
Particles >21µm		ASTM D7647	>40	e 48029	1	26
Particles >38µm		ASTM D7647	>10	e 338	0	1
Oil Cleanliness		ISO 4406 (c)	>20/18/14	e 28/28/25	🔺 23/19/10	🔺 23/20/14
Precipitate	scalar	Visual*	NONE	🔺 HEAVY	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	🔺 HEAVY	NONE	NONE
Appearance	scalar	Visual*	NORML	🔺 LAYRD	NORML	NORML
Emulsified Water	scalar	Visual*	>2	 1%	NEG	NEG
Free Water	scalar	Visual*		<u> </u>	NEG	NEG

Sample Rating Trend

Customer Id: ONTKEE Sample No.: WC0806463 Lab Number: 02559015 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 <u>gloria.gonzalez@wearcheck.com</u>

RECOMMENDED AC	ECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description		
Change Fluid			?	We recommend that you change the oil.		
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.		
Resample			?	Resample in 30-45 days to monitor this situation.		
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.		
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.		
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.		
Check Seals			?	Check seals and/or filters for points of contaminant entry.		
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.		

HISTORICAL DIAGNOSIS



11 Jul 2022 Diag: Kevin Marson

We recommend you service the filters on this component. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. Particles >4 μ m and oil cleanliness are abnormally high. Particles >6 μ m are notably high. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



view report



29 Mar 2021 Diag: Kevin Marson

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. We recommend you service the filters on this component. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) R&O OIL ISO 46. Please confirm. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. Particles >4µm are abnormally high. Particles >6µm are abnormally high. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



08 Jul 2020 Diag: Bill Quesnel

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you commend that you change the oil. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. Water contamination levels are severely high. Particles >14 µm are severely high. Particles >21 µm are severely high. Particles >64 µm are severely high. Particles >44 µm are severely high. Particles >71 µm are severely high. Particles >38 µm are abnormally high. There is a high concentration of water present in the oil. The ewater present. The white residue present in the sample is oil additive precipitate. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





OIL ANALYSIS REPORT

Area MANITOU FALLS GS Machine Id FP2G2 Component

Turbine Bearing Fluid ESSO TERESSO ISO 46 (--- GAL)

DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this oil. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend that you change the oil. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

🛑 Wear


Iron ppm levels are severe. Tin ppm levels are abnormal. Bearing wear is indicated. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil. Excessive free water present. Moderate concentration of visible dirt/debris present in the oil. High concentration of visible dirt/debris present in the oil.

Fluid Condition


The white residue present in the sample is oil additive precipitate. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.



		18/2003 00/12				
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0806463	WC0686279	WC0560631
Sample Date		Client Info		09 May 2023	11 Jul 2022	29 Mar 2021
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	ABNORMAL	ABNORMAL
CONTAMINATIC	N	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		5		
Iron	ppm	ASTM D5185(m)	>20	e 79	6	5
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	<1	<1	<1
Titanium	ppm	ASTM D5185(m)		3	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>20	1	0	<1
Lead	ppm	ASTM D5185(m)	>20	3	<1	<1
Copper	ppm	ASTM D5185(m)	>20	2	0	<1
Tin	ppm	ASTM D5185(m)	>20	<u> </u>	<1	<1
Antimony	ppm	ASTM D5185(m)		2	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1	0	<1
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)		<1	0	<1
Magnesium			0	<1	0	0
magnesiulli	ppm	ASTM D5185(m)	0	<1	0	0
Calcium	ppm ppm	ASTM D5185(m)		< 1	0 <1	<1
0	ppm ppm	. ,				
Calcium Phosphorus	ppm ppm	ASTM D5185(m)	0 2.4	0	<1	<1
Calcium	ppm ppm ppm	ASTM D5185(m) ASTM D5185(m)	0 2.4	0 0	<1 1	<1 1
Calcium Phosphorus Zinc	ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)	0 2.4	0 0 2	<1 1 <1	<1 1 <1
Calcium Phosphorus Zinc Sulfur	ppm ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)	0 2.4	0 0 2 1959	<1 1 <1 1857	<1 1 <1 1865 <1
Calcium Phosphorus Zinc Sulfur Lithium	ppm ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m)	0 2.4 0	0 0 2 1959 <1	<1 1 <1 1857 <1	<1 1 <1 1865 <1
Calcium Phosphorus Zinc Sulfur Lithium CONTAMINANTS	ppm ppm ppm ppm ppm ppm	ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) ASTM D5185(m) method	0 2.4 0 limit/base	0 0 2 1959 <1 current	<1 1 <1 1857 <1 history1	<1 1 <1 1865 <1 history2



OIL ANALYSIS REPORT



Ontario Power Generation KENORA PRODUCTION CENTRE, 200-60 FOURTEENTH ST N. KENORA, ON CA P9N 4M9 Contact: Josh Robinson josh.robinson@opg.com T: F:

history1

▲ 57082

9968

152

26

1

0

23/20/14

0.04

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NEG

NEG

44.4

history2

NORML

▲ 70270

9

1

0

0

▲

23/19/10

0.07

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NEG

41.9

4704

2004347

214397

48029

0.14

NONE

NONE

HEAVY

NONE

NONE

HEAVY

LAYRD

NORML

>10%

45.2

🔺 1%

338

2

1363311

CALA

ISO 17025:2017 Accredited

Laboratory

.

Laboratory

Sample No.

Lab Number

Unique Number

: WC0806463

: 02559015

: 5580055

To discuss this sample report, contact Customer Service at 1-800-268-2131.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

Diagnostician : Kevin Marson

: 23 May 2023

: 24 May 2023

Received

Test Package : IND 2 (Additional Tests: Bottom, PrtCount, TAN Man)

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

Diagnosed