

PROBLEM SUMMARY

DEGRADATION



Reciprocating Compressor


BITZER BSE 85K (--- LTR)




Sample Rating Trend



COMPONENT CONDITION SUMMARY





RECOMMENDATION

We recommend that you drain the oil from the component if this has not already been done. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE					
Acid Number (AN)	mg KOH/g	ASTM D974*	0.02	1.20					
Visc @ 40°C	cSt	ASTM D7279(m)	80	69.6					

Customer Id: DISEDM Sample No.: WC0816809 Lab Number: 02559485 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	We recommend that you drain the oil from the component if this has not already been done.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Area [235355] HILL PHOENIX RACK A #1537 (S/N 91228-2)

Reciprocating Compressor

BITZER BSE 85K (--- LTR)

DEGRADATION

Sample Rating Trend



DIAGNOSIS

Recommendation

We recommend that you drain the oil from the component if this has not already been done. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

The water content is negligible. There is no indication of any contamination in the oil.

Fluid Condition

The high AN level of the oil indicates the presence of oxi-polymerized products. The AN level is much higher than the recommended limit. Viscosity of sample indicates oil is within ISO 68 range, advise investigate. The oil is no longer serviceable.

				May2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0816809		
Sample Date		Client Info		10 May 2023		
Machine Age	yrs	Client Info		7		
Oil Age	yrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0		
Iron	ppm	ASTM D5185(m)	>50	0		
Chromium	ppm	ASTM D5185(m)	>10	0		
Nickel	ppm	ASTM D5185(m)		0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>25	<1		
Lead	ppm	ASTM D5185(m)	>25	0		
Copper	ppm	ASTM D5185(m)	>50	0		
Tin	ppm	ASTM D5185(m)	>15	0		
Antimony	ppm	ASTM D5185(m)		<1		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1		
Barium	ppm	ASTM D5185(m)	0	0		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)	0	0		
Magnesium	ppm	ASTM D5185(m)	0	0		
Calcium	ppm	ASTM D5185(m)	0	3		
Phosphorus	ppm	ASTM D5185(m)	1200	852		
Zinc	ppm	ASTM D5185(m)	0	2		
Sulfur	ppm	ASTM D5185(m)	0	6		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	3		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	<1		
Water	%	ASTM D6304*	>0.1	0.036		
ppm Water	ppm	ASTM D6304*	>1000	360.5		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2


1.20

Acid Number (AN)

mg KOH/g ASTM D974* 0.02



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: WC0816809 : 02559485

Received Diagnosed : 5580525

: 05 Jun 2023 Diagnostician : Kevin Marson

: 25 May 2023

Test Package : IND 2 (Additional Tests: KF, TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Display Fixtures - Loblaws 14740-111 Avenue Edmonton, AB

CA T5M 2P5 Contact: Ross Richards ross.richards@loblaw.ca

T: (780)232-2699

F: