


PROBLEM SUMMARY

PUMPHOUSE/HOOD COOLING PUMPS C - Hood Cooling 2 Electric Pump IB


Lube System

PETRO CANADA HYDREX AW 100 (1 GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.

| PROBLEMATIC TEST RESULTS | | | | | | | | |
|--------------------------|--------|--------------|-----------|-----------------|-----------------|------------------|--|--|
| Sample Status | | | | SEVERE | SEVERE | SEVERE | | |
| Particles >4µm | | ASTM D7647 | >5000 | 95253 | 184671 | 81356 | | |
| Particles >6µm | | ASTM D7647 | >1300 | 23382 | 46919 | 13710 | | |
| Particles >14μm | | ASTM D7647 | >160 | 1655 | 2055 | 4 09 | | |
| Particles >21µm | | ASTM D7647 | >40 | 427 | 342 | 6 0 | | |
| Oil Cleanliness | | ISO 4406 (c) | >19/17/14 | 24/22/18 | 25/23/18 | 2 4/21/16 | | |
| White Metal | scalar | Visual* | NONE | ▲ LIGHT | NONE | NONE | | |
| Debris | scalar | Visual* | NONE | ▲ LIGHT | NONE | NONE | | |
| PrtFilter | | | | | no image | no image | | |

Customer Id: LEWBOSC **Sample No.:** WC0850127 Lab Number: 02576246 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

| RECOMMENDED ACTIONS | | | | | | | |
|---------------------------|--------|------|---------|--|--|--|--|
| Action | Status | Date | Done By | Description | | | |
| Change Filter | | | ? | We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. | | | |
| Resample | | | ? | Resample in 30-45 days to monitor this situation. | | | |
| Alert | | | ? | We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified. | | | |
| Check Breathers | | | ? | The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. | | | |
| Check Dirt Access | | | ? | We advise that you check all areas where contaminants can enter the system. | | | |
| Check For Visual Metal | | | ? | We advise that you check for visible metal particles in the oil. | | | |
| Filter Fluid | | | ? | We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. | | | |

HISTORICAL DIAGNOSIS

100



31 May 2023 Diag: Bill Quesnel

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



21

27 Jan 2023 Diag: Kevin Marson



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. All component wear rates are normal. Particles >6µm are severely high. Particles >4µm are severely high. Oil Cleanliness are severely high. Particles >14µm are abnormally high. Particles >21µm are notably high. The water content is negligible. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. Viscosity of sample indicates oil is within ISO 150 range, advise investigate. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



13 Dec 2022 Diag: Kevin Marson





Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this oil. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Resample in 30-45 days to monitor this situation. All component wear rates are normal. Particles >6µm are severely high. Oil Cleanliness are severely high. Particles >4µm are severely high. Particles >14µm are severely high. Particles >21µm are abnormally high. Free water present. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





OIL ANALYSIS REPORT

Sample Rating Trend


ISO

PUMPHOUSE/HOOD COOLING PUMPS Machine Id C - Hood Cooling 2 Electric Pump IB

Component

Lube System

PETRO CANADA HYDREX AW 100 (1 GAL)





DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you check for visible metal particles in the oil. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified.

Wear

Light concentration of visible metal present.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil. Light concentration of visible dirt/debris present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code.

Fluid Condition

The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

| SAMPLE INFORM | IATION | method | limit/base | current | history1 | history2 |
|---------------|--------|-------------|------------|-------------|-------------|-------------|
| Sample Number | | Client Info | | WC0850127 | WC0824413 | WC0785675 |
| Sample Date | | Client Info | | 16 Aug 2023 | 31 May 2023 | 27 Jan 2023 |
| Machine Age | hrs | Client Info | | 0 | 0 | 0 |
| Oil Age | hrs | Client Info | | 0 | 0 | 0 |
| Oil Changed | | Client Info | | N/A | N/A | N/A |
| Sample Status | | | | SEVERE | SEVERE | SEVERE |
| WEAR METALS | | method | limit/base | current | history1 | history2 |

| WEAR METALS | | method | limit/base | current | history1 | history2 |
|-------------|-----|---------------|------------|---------|----------|----------|
| PQ | | ASTM D8184* | >DFLT | 0 | 0 | 0 |
| Iron | ppm | ASTM D5185(m) | >20 | 19 | 25 | 10 |
| Chromium | ppm | ASTM D5185(m) | >20 | <1 | 0 | 0 |
| Nickel | ppm | ASTM D5185(m) | >20 | <1 | 0 | 0 |
| Titanium | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| Silver | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| Aluminum | ppm | ASTM D5185(m) | >20 | <1 | <1 | <1 |
| Lead | ppm | ASTM D5185(m) | >20 | 0 | <1 | <1 |
| Copper | ppm | ASTM D5185(m) | >20 | <1 | <1 | <1 |
| Tin | ppm | ASTM D5185(m) | >20 | 0 | 0 | 0 |
| Antimony | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| Vanadium | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| Beryllium | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| Cadmium | ppm | ASTM D5185(m) | | 0 | 0 | 0 |
| | | | | | | |

| ADDITIVES | | method | limit/base | current | history1 | history2 |
|--------------|-----|---------------|------------|---------|----------|----------|
| Boron | ppm | ASTM D5185(m) | 0 | <1 | <1 | 3 |
| Barium | ppm | ASTM D5185(m) | 0 | <1 | 2 | <1 |
| Molybdenum | ppm | ASTM D5185(m) | 0 | 0 | 0 | 0 |
| Manganese | ppm | ASTM D5185(m) | 0 | <1 | <1 | <1 |
| Magnesium | ppm | ASTM D5185(m) | 0 | 1 | 1 | <1 |
| Calcium | ppm | ASTM D5185(m) | 50 | 52 | 57 | 43 |
| Phosphorus | ppm | ASTM D5185(m) | 330 | 351 | 363 | 349 |
| Zinc | ppm | ASTM D5185(m) | 430 | 412 | 376 | 313 |
| Sulfur | ppm | ASTM D5185(m) | 760 | 2584 | 2811 | 3647 |
| Lithium | ppm | ASTM D5185(m) | | <1 | <1 | <1 |
| CONTAMINANTS | ; | method | limit/base | current | history1 | history2 |


| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
|--------------|-----|---------------|------------|---------|----------|----------|
| Silicon | ppm | ASTM D5185(m) | >15 | 4 | 4 | 2 |
| Sodium | ppm | ASTM D5185(m) | | 5 | 8 | 8 |
| Potassium | ppm | ASTM D5185(m) | >20 | <1 | <1 | <1 |

| | Potassium | ppm | ASTM D5185(m) | >20 | <1 | <1 | <1 |
|------------|-----------------|------|---------------|------------|------------------|------------------|-------------------|
| 1000 | FLUID CLEANLIN | IESS | method | limit/base | current | history1 | history2 |
| | Particles >4µm | | ASTM D7647 | >5000 | 95253 | 184671 | 81356 |
| Top the | Particles >6µm | | ASTM D7647 | >1300 | 23382 | 46919 | 13710 |
| | Particles >14µm | | ASTM D7647 | >160 | 1655 | 2055 | 4 09 |
| | Particles >21µm | | ASTM D7647 | >40 | 427 | 4 342 | △ 60 |
| - T T TO B | Particles >38µm | | ASTM D7647 | >10 | 11 | 3 | 1 |
| | Particles >71µm | | ASTM D7647 | >3 | 1 | 0 | 0 |
| 1 | Oil Cleanliness | | ISO 4406 (c) | >19/17/14 | 2 4/22/18 | 2 5/23/18 | 4 24/21/16 |





OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory Sample No. Lab Number **Unique Number**

: WC0850127 : 02576246

: 5629306

Received Diagnosed

: 16 Aug 2023 : 17 Aug 2023

Diagnostician : Kevin Marson

2330 Regional Road #3, Door: BOSC8

NANTICOKE, ON CA NOA 1L0

Test Package : IND 2 (Additional Tests: Bottom, BottomAnalysis, FilterPatch, PQ, PrtFilter, TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131.

Contact: Tom Walden Thomas.Walden@stelco.com T: (519)587-4541

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Submitted By: Bob Melanson