

PROBLEM SUMMARY

Kingsbridge SP-13584 T21 (S/N 21750)

Wind Turbine Gearbox


CHEVRON PINNACLE WM 320 (--- LTR)


Sample Rating Trend






COMPONENT CONDITION SUMMARY







RECOMMENDATION

We recommend that you drain the oil from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS

Sample Status				SEVERE	SEVERE	ABNORMAL
Iron	ppm	ASTM D5185(m)	>75	△ 78	74	<u>^</u> 76
Zinc	ppm	ASTM D5185(m)	0	25	<u> </u>	18
Acid Number (AN)	mg KOH/g	ASTM D974*	0.7	1.53	1.54	<u>1.47</u>

Customer Id: VESTAS Sample No.: WC0783094 Lab Number: 02576923 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Bill Quesnel CLS,OMA II,MLA-III,LLA-I +1 (289)291-4641 x4641

Bill.Quesnel@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	We recommend that you drain the oil from the component if this has not already been done.			
Resample			?	We recommend an early resample to monitor this condition.			
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.			
Check Fluid Source			?	Confirm the source of the lubricant being utilized for top-up/fill.			

HISTORICAL DIAGNOSIS

12 Sep 2022 Diag: Bill Quesnel





We recommend that you drain the oil from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The water content is negligible. The system and fluid cleanliness is acceptable. Additive levels indicate the addition of a different brand, or type of oil. The high AN level of the oil indicates the presence of oxi-polymerized products. The AN level is much higher than the recommended limit. The oil is no longer serviceable.



21 Mar 2022 Diag: Kevin Marson

DEGRADATION



We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The water content is negligible. The system and fluid cleanliness is acceptable. The AN level is above the recommended limit. The oil is no longer serviceable.



28 Sep 2021 Diag: Bill Quesnel

DEGRADATION



We recommend that you drain the oil from the component if this has not already been done. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The water content is negligible. The system and fluid cleanliness is acceptable. The AN level is above the recommended limit. The oil is no longer serviceable.






OIL ANALYSIS REPORT

Kingsbridge SP-13584 T21 (S/N 21750)

Wind Turbine Gearbox

CHEVRON PINNACLE WM 320 (--- LTR)



Sample Rating Trend



DIAGNOSIS

Recommendation

We recommend that you drain the oil from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

Iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion.

Contamination

The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The water content is negligible. The system and fluid cleanliness is acceptable.

Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The high AN level of the oil indicates the presence of oxi-polymerized products. The AN level is much higher than the recommended limit. The oil is no longer serviceable.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0783094	WC0305836	WC0632662
Sample Date		Client Info		02 Aug 2023	12 Sep 2022	21 Mar 2022
Machine Age	yrs	Client Info		0	0	0
Oil Age	yrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*	>50	0	0	0
Iron	ppm	ASTM D5185(m)	>75	<u>^</u> 78	74	△ 76
Chromium	ppm	ASTM D5185(m)	>5	<1	<1	<1
Nickel	ppm	ASTM D5185(m)	>10	0	<1	<1
Titanium	ppm	ASTM D5185(m)	>10	0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>10	<1	<1	0
Lead	ppm	ASTM D5185(m)	>15	<1	<1	<1
Copper	ppm	ASTM D5185(m)	>10	2	1	<1
Tin	ppm	ASTM D5185(m)	>10	0	<1	0
Antimony	ppm	ASTM D5185(m)	>5	0	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	1	1	1
Barium	ppm	ASTM D5185(m)	0	0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)		<1	<1	<1
Magnesium	ppm	ASTM D5185(m)	0	<1	0	0
Calcium	ppm	()	0	1	<1	<1
Phosphorus	ppm	ASTM D5185(m)	300	232	240	247
Zinc	ppm	ASTM D5185(m)	0	<u>^</u> 25	<u>^</u> 21	18
Sulfur	ppm	ASTM D5185(m)	8000	7063	7182	7118
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>10	<1	<1	1
Sodium	ppm	ASTM D5185(m)	>10	6	6	4
Potassium	ppm	ASTM D5185(m)	>20	<1	1	<1
Water	%	ASTM D6304*	>0.02	0.013	0.011	0.004
ppm Water	ppm	ASTM D6304*	>200	131.9	115.7	45.9
INFRA-RED		method	limit/base	current	history1	history2
				ourront	,	•
Soot %	%	ASTM D7844*		0	0	0
	% Abs/cm					

Sulfation

Abs/.1mm ASTM D7415*


27.6

28.3

21.5



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number** Test Package

: WC0783094

: 02576923 : 5629983

To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Vestas American Wind Technology Inc. Received

Diagnosed : Bill Quesnel Diagnostician : IND 2 (Additional Tests: FT-IR, KF, KV100, PQ, PrtCount, TAN Man, VI)

: 23 Aug 2023

: 18 Aug 2023

1417 NW Everett Street Portland, OR US 97209

Contact: Nicole Philippi NiPhi@vestas.com

605

161

19

6

0

0

16/15/11

17.7

1.47

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NEG

335

36.6

156

T: (503)327-7683 F: (503)327-0247