

PROBLEM SUMMARY


Wide Cold Mill/Temper Mill

80" TEMPER MILL DRIVE LUBE (MILL OIL CELLAR) (WCM001) (S/N 100006023)


Component


Gear Lube System

PETRO CANADA ULTIMA EP 460 (2500 GAL)



COMPONENT CONDITION SUMMARY





RECOMMENDATION

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.

PROBLEMATIC TEST RESULTS							
Sample Status				SEVERE	SEVERE	SEVERE	
Particles >4µm		ASTM D7647	>5000	183797	164215	504271	
Particles >6µm		ASTM D7647	>1300	78716	83329	470593	
Particles >14µm		ASTM D7647	>320	<u> </u>	2519	330265	
Particles >21µm		ASTM D7647	>80	133	4 398	2 42697	
Oil Cleanliness		ISO 4406 (c)	>19/17/15	25/23/17	25/24/19	a 26/26/26	
Visc @ 40°C	cSt	ASTM D7279(m)	452.3	4 357	△ 364	416	

Customer Id: ALGSSM Sample No.: WC0752383 Lab Number: 02577810 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter			?	We recommend you service the filters on this component.		
Resample			?	Resample in 30-45 days to monitor this situation.		
Contact Required			?	Please contact your representative for information regarding the proper sampling kits for your service.		
Alert			?	NOTE: We recommend using IND 3 test kits,		
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.		
Check Seals			?	Check seals and/or filters for points of contaminant entry.		

HISTORICAL DIAGNOSIS

01 Mar 2023 Diag: Kevin Marson

X

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.Component wear rates appear to be normal (unconfirmed). Particles >14µm are severely high. Particles >6µm are severely high. Oil Cleanliness are severely high. Particles >4µm are severely high. Particles >21µm are abnormally high. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. Viscosity of sample indicates oil is within ISO 320 range, advise investigate. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



WATER



29 Jan 2021 Diag: Kevin Marson

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.Iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. ppm Water and water contamination levels are severe. Particles >38µm are severely high. Particles >6µm are severely high. Particles >71µm are severely high. Particles >14µm are severely high. Particles >21µm are severely high. Particles >4µm are severely high. Silicon ppm levels are abnormally high. There is a high concentration of water present in the oil. Free water present. Elemental level of silicon (Si) above normal indicating ingress of seal material. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid.



12 Nov 2020 Diag: Kevin Marson



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. Iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. Particles >6µm are severely high. Particles >4µm are severely high. Particles >14µm are abnormally high. Particles >21µm are notably high. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. Viscosity of sample indicates oil is within ISO 320 range, advise investigate. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT


Sample Rating Trend

Wide Cold Mill/Temper Mill

80" TEMPER MILL DRIVE LUBE (MILL OIL CELLAR) (WCM001) (S/N 100006023)

Gear Lube System

PETRO CANADA ULTIMA EP 460 (2500 GAL)





DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.

Component wear rates appear to be normal (unconfirmed).

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code.

Fluid Condition

Viscosity of sample indicates oil is within ISO 320 range, advise investigate. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

)		vlar2017 Sep2	017 Jan2018 Jul2018	May2019 Jan2020 Nov2020	Mar/2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0752383	WC0752203	WC0419568
Sample Date		Client Info		22 Aug 2023	01 Mar 2023	29 Jan 2021
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
Lance of the second						
Iron	ppm	ASTM D5185(m)	>150	99	95	<u>^</u> 251
Chromium	ppm ppm	ASTM D5185(m) ASTM D5185(m)		99 <1	95 <1	▲ 251 <1
	• •	. ,				
Chromium	ppm	ASTM D5185(m)	>10	<1	<1	<1
Chromium Nickel	ppm	ASTM D5185(m) ASTM D5185(m)	>10	<1 <1	<1 <1	<1 <1

ADDITIVES		method	limit/base	current	history1	history2
Cadmium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	<1
Antimony	ppm	ASTM D5185(m)	>5	0	<1	<1
Tin	ppm	ASTM D5185(m)	>10	4	4	6
Copper	ppm	ASTM D5185(m)	>50	6	5	5
Lead	ppm	ASTM D5185(m)	>100	2	2	2
Aluminum	ppm	ASTM D5185(m)	>25	<1	<1	1
Silver	ppm	ASTM D5185(m)		0	0	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Nickel	ppm	ASTM D5185(m)	>10	<1	<1	<1
Chromium	ppm	ASTM D5185(m)	>10	<1	<1	<1

Boron	ppm	ASTM D5185(m)	111	1	<1	3
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	<1
Manganese	ppm	ASTM D5185(m)		<1	<1	2
Magnesium	ppm	ASTM D5185(m)	2	<1	<1	1
Calcium	ppm	ASTM D5185(m)	6	7	3	8
Phosphorus	ppm	ASTM D5185(m)	482	174	176	251
Zinc	ppm	ASTM D5185(m)	3	24	21	11
Sulfur	ppm	ASTM D5185(m)	1458	4337	4575	10165
Lithium	ppm	ASTM D5185(m)		<1	<1	<1

CONTAMINAL	115	metnoa	ilmit/base	current	nistory i	nistory2
Silicon	ppm	ASTM D5185(m)	>50	4	4	△ 56
Sodium	ppm	ASTM D5185(m)		14	12	34
Potassium	ppm	ASTM D5185(m)	>20	5	4	4

FLUID CLEANLINESS	method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647	>5000	183797	164215	5 04271
Particles >6µm	ASTM D7647	>1300	78716	83329	470593
Particles >14μm	ASTM D7647	>320	<u> </u>	2519	330265
Particles >21µm	ASTM D7647	>80	<u> </u>	△ 398	2 42697
Particles >38μm	ASTM D7647	>20	4	15	93303
Particles >71µm	ASTM D7647	>4	2	3	18468
Oil Cleanliness	ISO 4406 (c)	>19/17/15	25/23/17	25/24/19	2 6/26/26
FLUID DEGRADATION	method	limit/base	current	history1	history2


Acid Number (AN)

mg KOH/g ASTM D974* 0.4

0.32



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number** Test Package

: WC0752383 : 02577810

: 5630870 : IND 2

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 ALGOMA STEEL INC. - STORES DEPT. Received : 23 Aug 2023 Diagnosed

: 25 Aug 2023 : Kevin Marson Diagnostician

SAULT STE MARIE, ON CA P6C 1K8 Contact: Algoma Reliability algomareliability@algoma.com T: (705)206-1059

301 WALLACE TERRACE

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: (705)945-3585