


# **PROBLEM SUMMARY**


Steering Gears **Steering Gear Port** 


**Rear Left Steering** 

PETRO CANADA HYDREX XV ALL SEASON HYDRAULIC OIL (--- GAL)



# **COMPONENT CONDITION SUMMARY**





# RECOMMENDATION

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	SEVERE	SEVERE		
Copper	ppm	ASTM D5185(m)	>50	<b>△</b> 96	<b>△</b> 95	<b>▲</b> 88		
Tin	ppm	ASTM D5185(m)	>5	<u> </u>	<u>^</u> 6	<u>^</u> 6		
Particles >4µm		ASTM D7647	>2500	<b>16833</b>	<b>2</b> 4383	93616		
Particles >6µm		ASTM D7647	>640	<b>▲</b> 682	<u> </u>	<b>15010</b>		
Oil Cleanliness		ISO 4406 (c)	>18/16/13	<u>^</u> 21/17/11	22/17/12	<b>2</b> 4/21/12		

Customer Id: VMASSEY **Sample No.:** WC0810845 Lab Number: 02579214 Test Package: MAR 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

# **RECOMMENDED ACTIONS**

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component.
Resample			?	We recommend an early resample to monitor this condition.

# HISTORICAL DIAGNOSIS

### 05 Aug 2023 Diag: Kevin Marson

WEAR



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. The filter change at the time of sampling has been noted. Resample in 30-45 days to monitor this situation. Copper and tin ppm levels are abnormal. There is a high amount of silt (particulates < 14 microns in size) present in the fluid. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.



### 08 Apr 2023 Diag: Kevin Marson

ISO



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.Copper and tin ppm levels are abnormal. There is a high amount of silt (particulates < 14 microns in size) present in the fluid. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.



# 29 Dec 2022 Diag: Kevin Marson

WEAR



The filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Copper ppm levels are noted. All other component wear rates are normal. Oil Cleanliness are abnormally high. Particles >14µm are abnormally high. Particles >6µm are abnormally high. Particles >21µm are notably high. The AN level is acceptable for this fluid. The fluid is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





# **OIL ANALYSIS REPORT**

Sample Rating Trend

# **WEAR**

# Steering Gears **Steering Gear Port**

Rear Left Steering

PETRO CANADA HYDREX XV ALL SEASON H

# DIAGNOSIS

# Recommendation

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

Copper and tin ppm levels are abnormal.

# Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the fluid.

# **Fluid Condition**

The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

DRAULIC OIL (	- GAL)					
SAMPLE INFORM	MATION	method	limit/base	Apr2023 Aug2023  Current	history1	history2
Sample Number		Client Info		WC0810845	WC0810850	WC0763478
Sample Date		Client Info		27 Aug 2023	05 Aug 2023	08 Apr 2023
Machine Age	hrs	Client Info		59188	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Not Changd	Oil Added	N/A
Sample Status				ABNORMAL	SEVERE	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185(m)	>50	2	2	3
Chromium	ppm	ASTM D5185(m)	>15	0	0	0
Nickel	ppm	ASTM D5185(m)	>5	0	0	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	<1	0
Aluminum	ppm	ASTM D5185(m)	>5	<1	<1	<1
_ead	ppm	ASTM D5185(m)	>10	3	3	3
Copper	ppm	ASTM D5185(m)	>50	<b>4</b> 96	<b>4</b> 95	<u></u> 88
- in	ppm	ASTM D5185(m)	>5	<u>^</u> 5	<u>^</u> 6	<u>^</u> 6
Antimony	ppm	ASTM D5185(m)		0	0	0
/anadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	0	<1	<1
Barium	ppm	ASTM D5185(m)	0	0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)	1	0	0	0
Magnesium	ppm	ASTM D5185(m)	0	1	<1	<1
Calcium	ppm	ASTM D5185(m)	100	97	96	100
Phosphorus	ppm	ASTM D5185(m)	670	699	704	719
Zinc	ppm	ASTM D5185(m)	850	846	850	843
Sulfur	ppm	ASTM D5185(m)	1600	1606	1631	1695
ithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	2	<1	<1
Sodium	ppm	ASTM D5185(m)		<1	<1	<1
Potassium	ppm	ASTM D5185(m)	>20	<1	<1	0
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	<b>16833</b>	24383	93616
Particles >6µm		ASTM D7647	>640	<u>^</u> 682	<u>1255</u>	15010
Particles >14μm		ASTM D7647	>80	16	23	21
Particles >21µm		ASTM D7647	>20	4	4	4
Particles >38µm		ASTM D7647	>4	0	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>18/16/13	<u> </u>	22/17/12	<b>2</b> 4/21/12
FLUID DEGRADA	TION	method	limit/base	current	history1	history2

Acid Number (AN)

mg KOH/g ASTM D974\* 0.60

0.69

0.74



# **OIL ANALYSIS REPORT**

