




PROBLEM SUMMARY



Area
Power Generation
 Machine Id
Main Engine #3 (S/N PAG00365)
 Component
3 Main Engine
 Fluid
CASTROL CRB Multi 15W-40 CK-4 (800 LTR)

Sample Rating Trend




FUEL




COMPONENT CONDITION SUMMARY

▲ Additives



▲ Fuel Dilution



RECOMMENDATION

We advise that you check the cylinder liner seals for deterioration to ensure that cooling water is not entering the sump. The oil change at the time of sampling has been noted. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. No other corrective action is recommended at this time. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MAR 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid. this testkit includes BN to determine the suitability of the oil for continued use.

PROBLEMATIC TEST RESULTS

Sample Status			ATTENTION	MARGINAL	ATTENTION
Boron	ppm	ASTM D5185(m)	▲ 52	55	▲ 45
Magnesium	ppm	ASTM D5185(m)	▲ 24	39	▲ 79
Calcium	ppm	ASTM D5185(m)	▲ 3591	3661	▲ 3425
Fuel	%	ASTM D7593* >4.0	▲ 2	▲ 2.4	<1.0

Customer Id: HORIZONENA
 Sample No.: WC0754032
 Lab Number: 02580552
 Test Package: MAR 1



To manage this report scan the QR code

To discuss the diagnosis or test data:
 Wes Davis +1 905-569-8600 x223
wesd@wearcheck.ca

To change component or sample information:
 Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Resample	---	---	?	We recommend an early resample to monitor this condition.
Contact Required	---	---	?	Please contact your representative for information regarding the proper sampling kits for your service.
Alert	---	---	?	NOTE: We recommend using MAR 3 test kits,
Check Fluid Source	---	---	?	Confirm the source of the lubricant being utilized for top-up/fill.
Check Seals	---	---	?	We advise that you check the cylinder liner seals for deterioration to ensure that cooling water is not entering the sump.

HISTORICAL DIAGNOSIS

07 Jun 2023 Diag: Wes Davis

FUEL



No corrective action is recommended at this time. Resample at the next service interval to monitor. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MAR 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid. this testkit includes BN to determine the suitability of the oil for continued use. Component wear rates appear to be normal (unconfirmed). Light fuel dilution occurring. No other contaminants were detected in the oil. The condition of the oil is acceptable for the time in service (unconfirmed). The condition of the oil is acceptable for the time in service.

view report



12 Mar 2023 Diag: Kevin Marson

ADDITIVES



We advise that you check the cylinder liner seals for deterioration to ensure that cooling water is not entering the sump. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MAR 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid. this testkit includes BN to determine the suitability of the oil for continued use. Component wear rates appear to be normal (unconfirmed). Elemental level of sodium (Na) and/or boron (B) indicates a possible cooling water leak. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service (unconfirmed).

view report



08 Nov 2022 Diag: Bill Quesnel

ADDITIVES



We advise that you check the cylinder liner seals for deterioration to ensure that cooling water is not entering the sump. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MAR 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid. this testkit includes BN to determine the suitability of the oil for continued use. Component wear rates appear to be normal (unconfirmed). Elemental level of sodium (Na) and/or boron (B) indicates a possible cooling water leak. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service (unconfirmed).

view report






OIL ANALYSIS REPORT



Area
Power Generation
Machine Id
Main Engine #3 (S/N PAG00365)
Component
3 Main Engine
Fluid
CASTROL CRB Multi 15W-40 CK-4 (800 LTR)

Sample Rating Trend



FUEL



DIAGNOSIS

Recommendation

We advise that you check the cylinder liner seals for deterioration to ensure that cooling water is not entering the sump. The oil change at the time of sampling has been noted. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. No other corrective action is recommended at this time. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using MAR 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid. this testkit includes BN to determine the suitability of the oil for continued use.

Wear

Component wear rates appear to be normal (unconfirmed).

Contamination

Elemental level of sodium (Na) and/or boron (B) indicates a possible cooling water leak. Light fuel dilution occurring. No other contaminants were detected in the oil.

Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service (unconfirmed). The condition of the oil is acceptable for the time in service.

SAMPLE INFORMATION

method	limit/base	current	history1	history2
Sample Number	Client Info	WC0754032	WC0754023	WC0754046
Sample Date	Client Info	22 Aug 2023	07 Jun 2023	12 Mar 2023
Machine Age	hrs	51464	50278	49458
Oil Age	hrs	998	820	1000
Oil Changed	Client Info	Changed	Not Changd	Changed
Sample Status		ATTENTION	MARGINAL	ATTENTION

CONTAMINATION

method	limit/base	current	history1	history2
Glycol	WC Method	NEG	NEG	NEG

WEAR METALS

method	limit/base	current	history1	history2	
Iron	ppm	ASTM D5185(m) >75	5	4	4
Chromium	ppm	ASTM D5185(m) >8	0	0	0
Nickel	ppm	ASTM D5185(m) >2	0	<1	0
Titanium	ppm	ASTM D5185(m) >3	0	<1	<1
Silver	ppm	ASTM D5185(m) >2	0	<1	0
Aluminum	ppm	ASTM D5185(m) >15	1	1	1
Lead	ppm	ASTM D5185(m) >18	2	1	1
Copper	ppm	ASTM D5185(m) >80	2	<1	1
Tin	ppm	ASTM D5185(m) >14	0	<1	<1
Antimony	ppm	ASTM D5185(m)	0	<1	0
Vanadium	ppm	ASTM D5185(m)	0	0	0
Beryllium	ppm	ASTM D5185(m)	0	0	0
Cadmium	ppm	ASTM D5185(m)	<1	<1	<1

ADDITIVES

method	limit/base	current	history1	history2	
Boron	ppm	ASTM D5185(m)	▲ 52	55	▲ 45
Barium	ppm	ASTM D5185(m)	0	0	0
Molybdenum	ppm	ASTM D5185(m)	34	33	30
Manganese	ppm	ASTM D5185(m)	<1	<1	<1
Magnesium	ppm	ASTM D5185(m)	▲ 24	39	▲ 79
Calcium	ppm	ASTM D5185(m)	▲ 3591	3661	▲ 3425
Phosphorus	ppm	ASTM D5185(m)	870	934	928
Zinc	ppm	ASTM D5185(m)	992	1009	1008
Sulfur	ppm	ASTM D5185(m)	2803	2988	2960
Lithium	ppm	ASTM D5185(m)	<1	<1	<1

CONTAMINANTS

method	limit/base	current	history1	history2	
Silicon	ppm	ASTM D5185(m) >20	3	4	3
Sodium	ppm	ASTM D5185(m) >75	1	<1	<1
Potassium	ppm	ASTM D5185(m) >20	<1	<1	<1
Fuel	%	ASTM D7593* >4.0	▲ 2	▲ 2.4	<1.0

INFRA-RED




method	limit/base	current	history1	history2	
Soot %	%	ASTM D7844*	0	0	0
Nitration	Abs/cm	ASTM D7624* >20	9.1	7.5	7.7
Sulfation	Abs./1mm	ASTM D7415* >30	19.8	17.2	17.9

FLUID DEGRADATION

method	limit/base	current	history1	history2	
Oxidation	Abs./1mm	ASTM D7414* >25	12.5	11.1	11.5






OIL ANALYSIS REPORT



PARAMETER	method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	VLITE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	NORML	NORML
Odor	scalar	Visual*	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>0.1	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG

FLUID PROPERTIES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D7279(m)	15.5	12.9	12.6

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Horizon Maritime Services Ltd. - Horizon Enabler
Sample No. : WC0754032 **Received** : 06 Sep 2023
Lab Number : 02580552 **Diagnosed** : 07 Sep 2023
Unique Number : 5633612 **Diagnostician** : Wes Davis
Test Package : MAR 1 (Additional Tests: FuelDilution, PercentFuel)
 To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.

87 Water Street, 2nd Floor
 St. John's, NL
 CA A1C 1A5
 Contact: Andrew Whalen
 chiefeng.enabler@horizonmaritime.com
 T:
 F: