

# **PROBLEM SUMMARY**

Sample Rating Trend

ISO

X


# SPRAY FOAM 1R1

Component

**Hydraulic Power Pack** 

CASTROL HYSPIN AWH-M ISO 68 (--- GAL)

## **COMPONENT CONDITION SUMMARY**



## **RECOMMENDATION**

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS									
Sample Status			SEVERE						
Particles >4μm	ASTM D7647	>5000	<b>130246</b>						
Particles >6µm	ASTM D7647	>1300	<b>33471</b>						
Particles >14μm	ASTM D7647	>160	<b>184</b>						
Oil Cleanliness	ISO 4406 (c)	>19/17/14	<b>24/22/15</b>						

Customer Id: HONALLPP2 Sample No.: CB0026008 Lab Number: 02586971 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Seals			?	Check seals and/or filters for points of contaminant entry.			

# HISTORICAL DIAGNOSIS



# **OIL ANALYSIS REPORT**

Sample Rating Trend

# **SPRAY FOAM 1R1**

**Hydraulic Power Pack** 

CASTROL HYSPIN AWH-M ISO 68 (--- GAL

## DIAGNOSIS

## Recommendation

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

#### Wear

All component wear rates are normal.

## Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.


### **Fluid Condition**

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

)				Oct2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		CB0026008		
Sample Date		Client Info		03 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	3		
Chromium	ppm	ASTM D5185(m)	>20	0		
Nickel	ppm	ASTM D5185(m)	>20	0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)	>20	<1		
Lead	ppm	ASTM D5185(m)	>20	0		
Copper	ppm	ASTM D5185(m)	>20	1		
Tin	ppm	ASTM D5185(m)	>20	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1		
Barium	ppm	ASTM D5185(m)		<1		
Molybdenum	ppm	ASTM D5185(m)		0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)		1		
Calcium	ppm	ASTM D5185(m)		45		
Phosphorus	ppm	ASTM D5185(m)		389		
Zinc	ppm	ASTM D5185(m)		430		
Sulfur	ppm	ASTM D5185(m)		5847		
Lithium		ASTM D5185(m)		<1		
	ppm	A01101 D0100(III)		<u> </u>		
CONTAMINANTS	5	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	1		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	<1		
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	130246		
Particles >6µm		ASTM D7647	>1300	33471		
Particles >14μm		ASTM D7647	>160	<u> </u>		
Particles >21µm		ASTM D7647	>40	34		
Particles >38µm		ASTM D7647	>10	5		
Particles >71µm		ASTM D7647	>3	2		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<b>2</b> 4/22/15		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
	1/011/	40714 0074				



## **OIL ANALYSIS REPORT**





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: CB0026008 : 02586971

: 5656037

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 04 Oct 2023 Diagnosed

: 04 Oct 2023 Diagnostician Test Package : IND 2 (Additional Tests: TAN MAN)

: Kevin Marson

Honda of Canada - Paint Plant 2 4700 TOTTENHAM ROAD, P.O. BOX 5000 STN MAIN ALLISTON, ON

CA L9R 1A2 Contact: Jeff Rathwell

jeffrey\_rathwell@hcm.honda.com T:

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: (705)435-4116