



PROBLEM SUMMARY

Sample Rating Trend

WATER



Area

3

Machine Id


3-101-MG Primary

Component

Crusher


Fluid

MOBIL MOBILGEAR 600 XP 320 (2900 LTR)




COMPONENT CONDITION SUMMARY


▲ Silicon (ppm)



Additives



Aluminum (ppm)



RECOMMENDATION

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this oil. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.

PROBLEMATIC TEST RESULTS

Sample Status		ABNORMAL	ABNORMAL	ABNORMAL
Silicon	ppm ASTM D5185(m) >100	▲ 160	▲ 144	9
Appearance	scalar Visual* NORML	▲ WGOIL	▲ WGOIL	NORML
Free Water	scalar Visual*	▲ 1%	NEG	NEG

Customer Id: STMBOW
Sample No.: WC0851467
Lab Number: 02591873
Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:
Kevin Marson +1 (289)291-4644 x4644
Kevin.Marson@wearcheck.com

To change component or sample information:
Gloria Gonzalez +1 (289)291-4643 x4643
gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter	MISSED	Nov 08 2023	?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.
Resample	MISSED	Nov 08 2023	?	We recommend an early resample to monitor this condition.
Contact Required	---	---	?	Please contact your representative for information regarding the proper sampling kits for your service.
Alert	MISSED	Nov 08 2023	?	NOTE: We recommend using IND 3 test kits,
Check Breathers	MISSED	Nov 08 2023	?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.
Check Fluid Source	MISSED	Nov 08 2023	?	Confirm the source of the lubricant being utilized for top-up/fill.
Check Water Access	MISSED	Nov 08 2023	?	We advise that you check for the source of water entry.
Check Seals	MISSED	Nov 08 2023	?	Check seals and/or filters for points of contaminant entry.
Filter Fluid	MISSED	Nov 08 2023	?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.

HISTORICAL DIAGNOSIS

16 Oct 2023 Diag: Kevin Marson

DIRT



We advise that you check all areas where dirt can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid. Component wear rates appear to be normal (unconfirmed). Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The water content is negligible. Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

view report



11 Oct 2023 Diag: Kevin Marson

DIRT



We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. We suspect that the abnormal contaminant(s) is the result of incorrect sampling technique. DISCLAIMER: Interpretation of results is based on the sample as received from the customer. The condition of the sample and the method of sampling cannot be verified. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. Viscosity of sample indicates oil is within ISO 220 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

view report



10 Oct 2023 Diag: Kevin Marson

DIRT



We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid. Aluminum ppm levels are noted. All other component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. Calcium and/or magnesium levels higher than normal indicating possible contamination with cement dust, advise investigate. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

view report





OIL ANALYSIS REPORT


Sample Rating Trend

WATER



Area
3
Machine Id
3-101-MG Primary

Component
Crusher
Fluid
MOBIL MOBILGEAR 600 XP 320 (2900 LTR)



DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this oil. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.

Wear

Component wear rates appear to be normal (unconfirmed).

Contamination

Free water present. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress.

Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORMATION

method	limit/base	current	history1	history2
Sample Number	Client Info	WC0851467	WC0842649	WC0851468
Sample Date	Client Info	23 Oct 2023	16 Oct 2023	11 Oct 2023
Machine Age	hrs Client Info	0	0	0
Oil Age	hrs Client Info	0	0	0
Oil Changed	Client Info	N/A	N/A	N/A
Sample Status		ABNORMAL	ABNORMAL	ABNORMAL

WEAR METALS

method	limit/base	current	history1	history2
Iron ppm	ASTM D5185(m) >200	87	86	7
Chromium ppm	ASTM D5185(m) >15	<1	<1	0
Nickel ppm	ASTM D5185(m) >15	<1	1	0
Titanium ppm	ASTM D5185(m)	2	2	0
Silver ppm	ASTM D5185(m)	<1	<1	<1
Aluminum ppm	ASTM D5185(m) >50	55	51	<1
Lead ppm	ASTM D5185(m) >100	17	16	<1
Copper ppm	ASTM D5185(m) >200	67	62	2
Tin ppm	ASTM D5185(m) >15	7	7	0
Antimony ppm	ASTM D5185(m) >5	0	0	0
Vanadium ppm	ASTM D5185(m)	0	0	0
Beryllium ppm	ASTM D5185(m)	0	0	0
Cadmium ppm	ASTM D5185(m)	0	0	0

ADDITIVES

method	limit/base	current	history1	history2
Boron ppm	ASTM D5185(m) 57	11	11	1
Barium ppm	ASTM D5185(m) 0.0	<1	<1	<1
Molybdenum ppm	ASTM D5185(m) 2.0	0	0	0
Manganese ppm	ASTM D5185(m) 0.0	<1	<1	0
Magnesium ppm	ASTM D5185(m) 0.0	26	24	0
Calcium ppm	ASTM D5185(m) 42	574	515	10
Phosphorus ppm	ASTM D5185(m) 399	294	278	255
Zinc ppm	ASTM D5185(m) 13	3	3	2
Sulfur ppm	ASTM D5185(m) 13649	10630	10193	1661
Lithium ppm	ASTM D5185(m)	<1	<1	<1

CONTAMINANTS






method	limit/base	current	history1	history2
Silicon ppm	ASTM D5185(m) >100	▲ 160	▲ 144	9
Sodium ppm	ASTM D5185(m)	3	4	1
Potassium ppm	ASTM D5185(m) >20	23	21	0
Water %	ASTM D6304* >0.1	0.004	0.010	---
ppm Water ppm	ASTM D6304* >1000	41.1	100.1	---

FLUID CLEANLINESS

method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647	238754	164035	334549
Particles >6µm	ASTM D7647 >320000	221540	154120	195777
Particles >14µm	ASTM D7647 >160000	117603	91576	20769
Particles >21µm	ASTM D7647 >40000	40800	43899	3995
Particles >38µm	ASTM D7647 >10000	77	351	93
Particles >71µm	ASTM D7647 >2500	0	2	2
Oil Cleanliness	ISO 4406 (c) >25/24	25/24	24/24	25/22



OIL ANALYSIS REPORT



FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.68	0.71	0.64	0.80

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	▲ LTMOD
Appearance	scalar	Visual*	NORML	▲ WGOIL	▲ WGOIL	NORML
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>0.1	.2%	.2%	NEG
Free Water	scalar	Visual*		▲ 1%	NEG	NEG

FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	275	314	314	▲ 204

SAMPLE IMAGES		method	limit/base	current	history1	history2
---------------	--	--------	------------	---------	----------	----------

Color			
Bottom			
PrtFilter	no image	no image	



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0851467 **Received** : 25 Oct 2023
Lab Number : **02591873** **Diagnosed** : 27 Oct 2023
Unique Number : 5668952 **Diagnostician** : Kevin Marson
Test Package : IND 2 (Additional Tests: KF, TAN Man)

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.

ST. MARYS CEMENT CO.
 400 BOWMANVILLE AVENUE
 BOWMANVILLE, ON
 CA L1C 7B5
 Contact: Lou Traiforos
 lou.traiforos@vcimentos.com
 T: (905)440-5874
 F: (905)623-4695