


PROBLEM SUMMARY







CATERPILLAR EXCAVATOR 01 (S/N SPN01708)


Hydraulic Power Pack

EXXON AW46 (40 GAL)



COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this oil. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS								
Sample Status				SEVERE				
Water	%	ASTM D6304*	>0.05	△ 0.123				
ppm Water	ppm	ASTM D6304*	>500	1234				
Particles >4µm		ASTM D7647	>5000	112912				
Particles >6µm		ASTM D7647	>1300	28087				
Particles >14µm		ASTM D7647	>160	417				
Oil Cleanliness		ISO 4406 (c)	>19/17/14	24/22/16				

Customer Id: QUI33BEL Sample No.: WC0726342 Lab Number: 02601233 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Bill Quesnel CLS, OMA II, MLA-III, LLA-I+1 (289)291-4641 x4641

Bill.Quesnel@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Water Access			?	We advise that you check for the source of water entry.			
Check Seals			?	Check seals and/or filters for points of contaminant entry.			
Filter Fluid			?	We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this oil.			

HISTORICAL DIAGNOSIS




OIL ANALYSIS REPORT



CATERPILLAR EXCAVATOR 01 (S/N SPN01708)

Hydraulic Power Pack

EXXON AW46 (40 GAL





DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this oil. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil. There is a moderate concentration of water present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

_)						
		-		Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0726342		
Sample Date		Client Info		05 Dec 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	2		
Chromium	ppm	ASTM D5185(m)	>20	0		
Nickel	ppm	ASTM D5185(m)	>20	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)	>20	<1		
Lead	ppm	ASTM D5185(m)	>20	<1		
Copper	ppm	ASTM D5185(m)		1		
Tin	ppm	ASTM D5185(m)	>20	0		
Antimony	ppm	ASTM D5185(m)	720	0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
	ррпп	. ,		•		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		33		
Barium	ppm	ASTM D5185(m)		<1		
Molybdenum	ppm	ASTM D5185(m)		22		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)		309		
Calcium	ppm	ASTM D5185(m)		590		
Phosphorus	ppm	ASTM D5185(m)		619		
Zinc	ppm	ASTM D5185(m)		740		
Sulfur	ppm	ASTM D5185(m)		2309		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	4		
Sodium	ppm	ASTM D5185(m)		3		
Potassium	ppm	ASTM D5185(m)	>20	0		
Water	%	ASTM D6304*	>0.05	△ 0.123		
ppm Water	ppm	ASTM D6304*	>500	1234		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>5000	112912		
Particles >6µm		ASTM D7647	>1300	28087		
Particles >14μm		ASTM D7647	>160	<u>▲</u> 417		
Particles >21µm		ASTM D7647	>40	55		
Particles >38µm		ASTM D7647	>10	2		
Particles >71μm		ASTM D7647	>3	1		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	24/22/16		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Sample No. Lab Number **Unique Number**

: WC0726342 : 02601233

: 5694318

Received Diagnosed

: 07 Dec 2023 Diagnostician : Bill Quesnel

Test Package : IND 2 (Additional Tests: KF, TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

33 VERMILYEA RD. BELLEVILLE, ON CA K8N 4Z5 Contact: Ryan Griffin Ryan@qhsi.ca T: (613)969-6588 F:

Report Id: QUI33BEL [WCAMIS] 02601233 (Generated: 12/07/2023 12:28:39) Rev: 1