

# **PROBLEM SUMMARY**


# **BUILDING 51 - CEREAL PRODUCTS**

SCRUBBER BLOWDOWN TANK PUMP #2 NORTH BEARING FRAME (S/N 51P102)

Component


Bearing


**LUBRICATION ENG MULTILEC 6803 (--- LTR)** 







# **COMPONENT CONDITION SUMMARY**









## RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We recommend either performing an oil change or oil filtration. We cannot recommend specific action as we have limited information with regards to reservoir capacity and/or lubricant type. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS											
Sample Status				SEVERE	SEVERE						
PQ		ASTM D8184*		<u> </u>	<b>3</b> 04						
Iron	ppm	ASTM D5185(m)	>20	<u> </u>	<b>217</b>						
Particles >4µm		ASTM D7647	>10000	<b>226831</b>	202158						
Particles >6µm		ASTM D7647	>2500	<b>178480</b>	172662						
Particles >14µm		ASTM D7647	>160	<b>20812</b>	<b>49566</b>						
Particles >21µm		ASTM D7647	>40	<b>644</b>	7747						
Oil Cleanliness		ISO 4406 (c)	>20/18/14	<b>25/25/22</b>	<b>2</b> 5/25/23						
Visc @ 40°C	cSt	ASTM D7279(m)	64.7	<u> </u>	<u>^</u> 209						

**Customer Id: HIRWIN Sample No.:** WC0865418 Lab Number: 02601320 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

#### **RECOMMENDED ACTIONS** Action **Status** Date Done By Description ? Resample Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type Information Required ? and micron rating with next sample. The air breather requires service. If unrated, we recommend that you replace with a **Check Breathers** ? suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather We advise that you check all areas where contaminants can enter the **Check Dirt Access** ? system. We recommend either performing an oil change or oil filtration. We cannot recommend Filter Fluid specific action as we have limited information with regards to reservoir capacity and/or lubricant type.

# HISTORICAL DIAGNOSIS

WEAR



#### 01 Dec 2023 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. We recommend either performing an oil change or oil filtration. We cannot recommend specific action as we have limited information with regards to reservoir capacity and/or lubricant type. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Iron ppm levels are severe. PQ levels are severe. Bearing wear is indicated. The very high ferrous density (PQ) index indicates that severe wear is occurring. There is a high amount of particulates (2 to 100 microns in size) present in the oil. Viscosity of sample indicates oil is within SAE 90 range, advise investigate. The oil is no longer serviceable as a result of the abnormal and/or severe wear.





# **OIL ANALYSIS REPORT**


# BUILDING 51 - CEREAL PRODUCTS

SCRUBBER BLOWDOWN TANK PUMP #2 NORTH BEARING FRAME (S/N 51P102)

Component

Bearing

**LUBRICATION ENG MULTILEC 6803 (--- LTR)** 





# **DIAGNOSIS** Recommendation

We advise that you check all areas where contaminants can enter the system. We recommend either performing an oil change or oil filtration. We cannot recommend specific action as we have limited information with regards to reservoir capacity and/or lubricant type. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

## Wear

PQ levels are abnormal. Iron ppm levels are abnormal. Bearing wear is indicated. The high ferrous density (PQ) index indicates that abnormal wear is occurring.

# Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil.


### Fluid Condition

Viscosity of sample indicates oil is within SAE 80W90 range, advise investigate. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

IR)			Dec2023	Dec2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0865418	WC0865417	
Sample Date		Client Info		01 Dec 2023	01 Dec 2023	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		Not Changd	Not Changd	
Sample Status				SEVERE	SEVERE	
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG	NEG	
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		<b>197</b>	<b>3</b> 04	
Iron	ppm	ASTM D5185(m)	>20	<u> 111</u>	<b>1</b> 217	
Chromium	ppm	ASTM D5185(m)	>20	<1	<1	
Nickel	ppm	ASTM D5185(m)	>20	<1	<1	
Titanium	ppm	ASTM D5185(m)		0	0	
Silver	ppm	ASTM D5185(m)		<1	<1	
Aluminum	ppm	ASTM D5185(m)	>20	<1	<1	
Lead	ppm	ASTM D5185(m)	>20	0	0	
Copper	ppm	ASTM D5185(m)	>20	<1	<1	
Tin	ppm	ASTM D5185(m)	>20	0	0	
Antimony	ppm	ASTM D5185(m)		0	0	
Vanadium	ppm	ASTM D5185(m)		0	0	
Beryllium	ppm	ASTM D5185(m)		0	0	
Cadmium	ppm	ASTM D5185(m)		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		77	68	
Barium	ppm	ASTM D5185(m)		3	<1	
Molybdenum	ppm	ASTM D5185(m)		0	0	
Manganese	ppm	ASTM D5185(m)		1	<1	
Magnesium	ppm	ASTM D5185(m)		0	0	
Calcium	ppm	ASTM D5185(m)		5	2	
Phosphorus	ppm	ASTM D5185(m)		1041	1050	
Zinc	ppm	ASTM D5185(m)		6	3	
Sulfur	ppm	ASTM D5185(m)		15102	14968	
Lithium	ppm	ASTM D5185(m)		2	<1	
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	2	<1	
Sodium	ppm	ASTM D5185(m)		3	2	
Potassium	ppm	ASTM D5185(m)	>20	<1	0	



# OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: WC0865418

: 5694405

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : 02601320

Received : 06 Dec 2023 Diagnosed : 07 Dec 2023

Diagnostician : Kevin Marson

HIRAM WALKER & SONS LTD. 2072 RIVERSIDE DRIVE EAST, BOX 2518 WINDSOR, ON

**CA N8Y 4S5** Contact: Matt Morand

Test Package : IND 2 ( Additional Tests: PQ, TAN Man ) To discuss this sample report, contact Customer Service at 1-800-268-2131.

matt.morand@pernod-ricard.com T: (519)561-5359

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

F: (519)971-5719 Contact/Location: Matt Morand - HIRWIN