

# **PROBLEM SUMMARY**

Sample Rating Trend



Area **8** Machine Id


# 8-310-B FM #1 Separator Bearings Lube


Component \_\_\_\_


**Reservoir Bearing** 


**MOBIL DTE OIL EXTRA HEAVY (40 LTR)** 


### **COMPONENT CONDITION SUMMARY**











### RECOMMENDATION

We advise that you check all areas where dirt can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESUL	TS

Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
Iron	ppm	ASTM D5185(m)	>25	<u>▲</u> 61	<b>△</b> 53	<b>△</b> 43
Aluminum	ppm	ASTM D5185(m)	>3	<u>^</u> 7	<u>^</u> 6	<u> 5</u>
Phosphorus	ppm	ASTM D5185(m)		<b>102</b>	<b>△</b> 35	<u>^</u> 79
Zinc	ppm	ASTM D5185(m)		<b>14</b>	<u>^</u> 22	<u>45</u>
Sulfur	ppm	ASTM D5185(m)		<u>▲</u> 5599	<b>4467</b>	<u></u> 5165
Silicon	ppm	ASTM D5185(m)	>15	<b>^</b> 26	<u>^</u> 22	<u>^</u> 20
Visc @ 40°C	cSt	ASTM D7279(m)	146	<b>189</b>	149	151

Customer Id: STMBOW Sample No.: WC0869931 Lab Number: 02602006 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

### RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.
Resample			?	We recommend an early resample to monitor this condition.
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.
Check Dirt Access			?	We advise that you check all areas where dirt can enter the system.
Check Fluid Source			?	Confirm the source of the lubricant being utilized for top-up/fill.
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.

### HISTORICAL DIAGNOSIS

11 Sep 2023 Diag: Bill Quesnel



We advise that you check all areas where dirt can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Iron ppm levels are abnormal. Aluminum ppm levels are noted. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. High amount of ingressed dirt has caused abrasive wear to the component. Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.





17 May 2023 Diag: Kevin Marson

We advise that you check all areas where dirt can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition. Iron ppm levels are abnormal. Aluminum ppm levels are noted. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. High amount of ingressed dirt has caused abrasive wear to the component. Additive levels indicate the addition of a different brand, or type of oil. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.





27 Nov 2022 Diag: Kevin Marson

We advise that you check all areas where dirt can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend an early resample to monitor this condition.Iron ppm levels are abnormal. Aluminum ppm levels are noted. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. High amount of ingressed dirt has caused abrasive wear to the component. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.






# **OIL ANALYSIS REPORT**

8 Machine Id

# 8-310-B FM #1 Separator Bearings Lube

Reservoir Bearing

**MOBIL DTE OIL EXTRA HEAVY (40 LTR)** 



### **DIAGNOSIS**

#### Recommendation

We advise that you check all areas where dirt can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition.

#### Wear

Iron ppm levels are abnormal. Aluminum ppm levels are noted. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion.

### Contamination

Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. High amount of ingressed dirt has caused abrasive wear to the component.


## ▲ Fluid Condition

Viscosity of sample indicates oil is within SAE 90 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORM	ΛΑΤΙΟΝ	method	limit/base	current	history1	history2
	717 (11014		III III Dasc			
Sample Number		Client Info		WC0869931 29 Nov 2023	WC0842772	WC0818202
Sample Date	bro	Client Info			11 Sep 2023	17 May 2023
Machine Age Oil Age	hrs	Client Info		0	0	0
Oil Changed	1115	Client Info		N/A	N/A	N/A
Sample Status		Ciletit IIIIO		ABNORMAL	ABNORMAL	ABNORMAL
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		16	0	0
Iron	ppm	ASTM D5185(m)	>25	<u></u> 61	<b>△</b> 53	<b>4</b> 3
Chromium	ppm	ASTM D5185(m)	>20	<1	<1	<1
Nickel	ppm	ASTM D5185(m)	>20	<1	<1	<1
Titanium	ppm	ASTM D5185(m)		0	<1	<1
Silver	ppm	ASTM D5185(m)		<1	0	0
Aluminum	ppm	ASTM D5185(m)	>3	<u> </u>	<u>6</u>	<u> 5</u>
Lead	ppm	ASTM D5185(m)	>6	<1	0	0
Copper	ppm	ASTM D5185(m)	>60	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>6	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		3	5	4
Barium	ppm	ASTM D5185(m)		<1	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	<1
Manganese	ppm	ASTM D5185(m)		0	<1	<1
Magnesium	ppm	ASTM D5185(m)		5	4	3
Calcium	ppm	ASTM D5185(m)		131	107	102
Phosphorus	ppm	ASTM D5185(m)		<b>102</b>	<b>△</b> 35	<u>^</u> 79
Zinc	ppm	ASTM D5185(m)		<u> </u>	<u>^</u> 22	<b>△</b> 45
Sulfur	ppm	ASTM D5185(m)		<b>△</b> 5599	<b>4467</b>	<u></u> 5165
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	<b>^</b> 26	<u>^</u> 22	<u>^</u> 20
Sodium	ppm	ASTM D5185(m)		<1	<1	<1
Potassium	ppm	ASTM D5185(m)	>20	4	3	2
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		0.11	0.04	0.13



## **OIL ANALYSIS REPORT**



To discuss this sample report, contact Customer Service at 1-800-268-2131.

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

T: (905)440-5874 F: (905)623-4695

lou.traiforos@vcimentos.com