



PROBLEM SUMMARY

Area BRUCE B/8/43230 Machine Id 8-43230-P4-P IB Brg Drn Component


Inboard Bearing Fluid ESSO NUTO H ISO 46 (--- GAL)

COMPONENT CONDITION SUMMARY










Ferrous Alloys



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a compression test. We recommend either performing an oil change or oil filtration. We cannot recommend specific action as we have limited information with regards to reservoir capacity and/or lubricant type. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS								
Sample Status		SEVERE	SEVERE	SEVERE				
Chromium	ppm	ASTM D5185(m)	>5	<u> </u>	0	0		
Lead	ppm	ASTM D5185(m)	>5	<mark> 8</mark>	1	2		
Copper	ppm	ASTM D5185(m)	>5	6 57	5	8		
Tin	ppm	ASTM D5185(m)	>5	<u> </u>	<1	<1		
Ferrous Sliding	Scale 0-10	ASTM D7684*		 1				
Ferrous Cutting	Scale 0-10	ASTM D7684*				A 1		
Silicon	ppm	ASTM D5185(m)	>5	• 17	▲ 7	9		
Particles >4µm		ASTM D7647	>5000	🛑 169532	97733	1 43797		
Particles >6µm		ASTM D7647	>1300	e 123574	18240	939803		
Particles >14µm		ASTM D7647	>320	9288	279	5 08		
Particles >21µm		ASTM D7647	>80	<u> </u>	33	43		
Oil Cleanliness		ISO 4406 (c)	>19/17/15	e 25/24/20	• 24/21/15	• 24/22/16		

Customer Id: BRUTIV Sample No.: WC0744593 Lab Number: 02602854 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 <u>Kevin.Marson@wearcheck.com</u>

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 <u>gloria.gonzalez@wearcheck.com</u>

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Monitor			?	We advise that you perform a compression test.			
Resample			?	Resample in 30-45 days to monitor this situation.			
Information Required		? We advise that you perform a compression ? Resample in 30-45 days to monitor this sit ? NOTE: Please provide information regardi and micron rating with next sample. ? The air breather requires service. If unrated, we re suitable micron rated and/or desiccant air breather service/replace the breather. ? We advise that you check all areas where system. We recommend either performing an oil change or We recommend either performing an oil change or	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.				
Check Breathers			? We advise that you perform a compression ? Resample in 30-45 days to monitor this since ? NOTE: Please provide information regards and micron rating with next sample. ? NOTE: Please provide information regards and micron rating with next sample. ? The air breather requires service. If unrated, we resultable micron rated and/or desiccant air breather service/replace the breather. ? We advise that you check all areas where system. ? We recommend either performing an oil change o specific action as we have limited information with	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.			
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.			
Filter Fluid			?	We recommend either performing an oil change or oil filtration. We cannot recommend specific action as we have limited information with regards to reservoir capacity and/or lubricant type.			

HISTORICAL DIAGNOSIS

20 Jul 2023 Diag: Kevin Marson



Check seals and/or filters for points of contaminant entry. We advise that you check all areas where dirt can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Wear particle analysis indicates that the ferrous cutting particles are marginal. All other component wear rates are normal. Cutting wear particles are caused by either hard protuberances (mis-aligned components, etc.), or abrasives entering the system and embedding themselves in softer materials (sand, etc.), and gouging out mating surfaces. There is a high amount of silt (particulates < 14 microns in size) present in the oil. Elemental level of slove normal indicating ingress of seal material. The water content is negligible. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



view report

26 Apr 2023 Diag: Kevin Marson



Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Copper ppm levels are abnormal. Wear particle analysis indicates that the ferrous cutting particles are marginal. All other component wear rates are normal. Cutting wear particles are caused by either hard protuberances (mis-aligned components, etc.), or abrasives entering the system and embeding themselves in softer materials (sand, etc.), and gouging out mating surfaces. Particles >6µm are severely high. Oil Cleanliness are severely high. Particles >4µm are severely high. Silicon ppm levels are abnormally high. Particles >14µm are notably high. Elemental level of silicon (Si) above normal indicating ingress of seal material. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

01 Feb 2023 Diag: Kevin Marson



Check seals and/or filters for points of contaminant entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Copper ppm levels are abnormal. Bearing wear is indicated. The direct-reading & analytical ferrographic results are normal indicating no abnormal wear in the system. Particles >4µm and oil cleanliness are severely high. Silicon ppm levels are abnormally high. Particles >6µm are abnormally high. Elemental level of silicon (Si) above normal indicating ingress of seal material. The water content is negligible. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.





OIL ANALYSIS REPORT

BRUCE B/8/43230 Machine Id 8-43230-P4-P IB Brg Drn

Inboard Bearing Fluid ESSO NUTO H ISO 46 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a compression test. We recommend either performing an oil change or oil filtration. We cannot recommend specific action as we have limited information with regards to reservoir capacity and/or lubricant type. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

🛑 Wear


Copper ppm levels are severe. Lead, tin and chromium ppm levels are abnormal. Wear particle analysis indicates that the ferrous cutting and ferrous sliding particles are marginal. Bearing wear is indicated. Cutting wear particles are caused by either hard protuberances (mis-aligned components, etc.), or abrasives entering the system and embedding themselves in softer materials (sand, etc.), and gouging out mating surfaces. Sliding wear particles are caused from metal on metal contact, and may be the result of high loads, speeds, or temperature, insufficient lubrication, or lack of anti-wear or extreme pressure additives.

Contaminants

There is a high amount of particulates (2 to 100 microns in size) present in the oil. Elemental level of silicon (Si) above normal indicating ingress of seal material. The water content is negligible. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code.

Oil Condition

The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.




SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0744593	WC0744561	WC074454
Sample Date		Client Info		06 Dec 2023	20 Jul 2023	26 Apr 202
Machine Age	kms	Client Info		0	0	0
Oil Age	kms	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185(m)	>10	2	0	<1
Chromium	ppm	ASTM D5185(m)	>5	<u> </u>	0	0
Nickel	ppm	ASTM D5185(m)	>5	<1	0	0
Titanium	ppm	ASTM D5185(m)	>5	0	0	0
Silver	ppm	ASTM D5185(m)		<1	0	0
Aluminum	ppm	ASTM D5185(m)	>5	<1	<1	0
Lead	ppm	ASTM D5185(m)	>5	<mark>/</mark> 8	1	2
Copper	ppm	ASTM D5185(m)	>5	e 57	5	▲ 8
Tin	ppm	ASTM D5185(m)	>5	A 7	<1	<1
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history
Boron	ppm	ASTM D5185(m)	0	<1	0	0
Barium	ppm	ASTM D5185(m)	0	<1	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)	5	0	<1	0
Calcium	ppm	ASTM D5185(m)	50	53	54	55
Phosphorus	ppm	ASTM D5185(m)	330	348	383	375
Zinc	ppm	ASTM D5185(m)	410	444	455	432
Sulfur	ppm	ASTM D5185(m)	2700	5776	5634	5519
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANT	S	method	limit/base	current	history1	history
Silicon	ppm	ASTM D5185(m)	>5	• 17	 7	9
Sodium	ppm	ASTM D5185(m)	>5	<1	0	0
Potassium	ppm	ASTM D5185(m)	>20	0	<1	0
Water	%	ASTM D6304*	>0.005	0.002	0.00	0.00
opm Water	ppm	ASTM D6304*	>50	18	0.00	0.00
FLUID CLEANLI	NESS	method	limit/base	current	history1	history
Particles >4µm		ASTM D7647	>5000	e 169532	97733	1 43797
Particles >6µm		ASTM D7647	>1300	e 123574	18240	939803
Particles >14µm		ASTM D7647	>320	9288	279	5 08
Particles >21µm		ASTM D7647	>80	<u> </u>	33	43
Particles >38µm		ASTM D7647	>20	3	3	1
Dortiolog 71um		ASTM D7647	>4	0	2	1
Particles >71µm				•		

Contact/Location: Pierre Adouki - BRUTIV



OIL ANALYSIS REPORT






FERROGRAPHY REPORT

Area BRUCE B/8/43230 Machine Id 8-43230-P4-P IB Brg Drn Component


Inboard Bearing Fluid ESSO NUTO H ISO 46 (--- GAL)



DR-FERROGRAP	ΉY	method	limit/base	current	history1	history2
Large Particles		DR-Ferr*		25.0	2.5	2.3
Small Particles		DR-Ferr*		10.3	1.4	1.1
Total Particles		DR-Ferr*	>	35.3	3.9	3.4
Large Particles Percentage	%	DR-Ferr*		41.6	28.2	35.3
Severity Index		DR-Ferr*		368	3	3
FERROGRAPHY		method	limit/base	current	history1	history2
Ferrous Rubbing	Scale 0-10	ASTM D7684*		4	2	2
Ferrous Sliding	Scale 0-10	ASTM D7684*		4 1		
Ferrous Cutting	Scale 0-10	ASTM D7684*		4 1	 1	 1
Ferrous Rolling	Scale 0-10	ASTM D7684*		1	1	1
Ferrous Break-in	Scale 0-10	ASTM D7684*				
Ferrous Spheres	Scale 0-10	ASTM D7684*				
Ferrous Black Oxides	Scale 0-10	ASTM D7684*				
Ferrous Red Oxides	Scale 0-10	ASTM D7684*				
Ferrous Corrosive	Scale 0-10	ASTM D7684*		1		
Ferrous Other	Scale 0-10	ASTM D7684*				
Nonferrous Rubbing	Scale 0-10	ASTM D7684*				
Nonferrous Sliding	Scale 0-10	ASTM D7684*				
Nonferrous Cutting	Scale 0-10	ASTM D7684*				
Nonferrous Rolling	Scale 0-10	ASTM D7684*				
Nonferrous Other	Scale 0-10	ASTM D7684*				
Carbonaceous Material	Scale 0-10	ASTM D7684*				
Lubricant Degradation	Scale 0-10	ASTM D7684*				
Sand/Dirt	Scale 0-10	ASTM D7684*		1	1	1
Fibres	Scale 0-10	ASTM D7684*				
Spheres	Scale 0-10	ASTM D7684*				
Other	Scale 0-10	ASTM D7684*		2	1	1

WEAR

Copper ppm levels are severe. Lead, tin and chromium ppm levels are abnormal. Wear particle analysis indicates that the ferrous cutting and ferrous sliding particles are marginal. Bearing wear is indicated. Cutting wear particles are caused by either hard protuberances (mis-aligned components, etc.), or abrasives entering the system and embedding themselves in softer materials (sand, etc.), and gouging out mating surfaces. Sliding wear particles are caused from metal on metal contact, and may be the result of high loads, speeds, or temperature, insufficient lubrication, or lack of anti-wear or extreme pressure additives.



This page left intentionally blank