


# **PROBLEM SUMMARY**


# (C-FIYQ) Machine Id [C-FIYQ] CESSNA 414 218881-R


**Right Piston Aircraft Engine** 

SHELL AEROSHELL W 100 (12 GAL)









### RECOMMENDATION

We advise that you check the engine magneto timing. We advise that you check the engine tuning and timing. We advise that you check for excessive valve and valve guide clearance. We advise that you check for a possible too-lean mixture, or an overadvanced ignition timing. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS										
Sample Status				SEVERE	ABNORMAL					
Chromium	ppm	ASTM D5185(m)	>20	<b>127</b>	<b>A</b> 89					
Nickel	ppm	ASTM D5185(m)	>15	<b>4</b> 0	17					
Aluminum	ppm	ASTM D5185(m)	>25	<b>△</b> 68	<u>^</u> 64					

Customer Id: ITPLON Sample No.: WC0844054 Lab Number: 02603184 Test Package: AVI 1



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS								
Action	Status	Date	Done By	Description				
Resample			?	We recommend an early resample to monitor this condition.				
Check Combustion			?	We advise that you check the engine tuning and timing.				
Check			?	We advise that you check for excessive valve and valve guide clearance.				
Check Timing			?	We advise that you check the engine magneto timing.				

## HISTORICAL DIAGNOSIS

### 10 Aug 2023 Diag: Kevin Marson

WEAR



We advise that you check the engine magneto timing. We advise that you check for a possible too-lean mixture, or an over-advanced ignition timing. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AVIATION ENGINE OIL SAE 15W50. Please confirm. Aluminum and chromium ppm levels are abnormal. Ring wear is indicated. High Aluminum (Al) level indicates abnormal bearing wear. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.





# **OIL ANALYSIS REPORT**

# (C-FIYQ) Machine Id [C-FIYQ] CESSNA 414 218881-R

**Right Piston Aircraft Engine** 

**SHELL AEROSHELL W 100 (12 GAL)** 

# Sample Rating Trend Aug/2023 Dec/2023



## DIAGNOSIS

### Recommendation

We advise that you check the engine magneto timing. We advise that you check the engine tuning and timing. We advise that you check for excessive valve and valve guide clearance. We advise that you check for a possible too-lean mixture, or an over-advanced ignition timing. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

### Wear

Chromium and nickel ppm levels are severe. Aluminum ppm levels are abnormal. Ring wear is indicated. Exhaust valve wear is indicated. High Aluminum (AI) level indicates abnormal bearing wear. A cylinder ring may be cracked or broken.

#### Contamination

There is no indication of any contamination in the oil.


### **Fluid Condition**

The oil is no longer serviceable as a result of the abnormal and/or severe wear.

			Aug2023	Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0844054	WC0844063	
Sample Date		Client Info		11 Dec 2023	10 Aug 2023	
TSN	hrs	Client Info		5907	0	
TSO	hrs	Client Info		312	269	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		Changed	Changed	
Sample Status				SEVERE	ABNORMAL	
CONTAMINATION	V	method	limit/base	current	history1	history2
Fuel		WC Method	>4.0	<1.0	<1.0	
Water		WC Method	>0.1	NEG	NEG	
Glycol		WC Method		NEG	NEG	
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		41	11	
Iron	ppm	ASTM D5185(m)	>90	150	90	
Chromium	ppm	ASTM D5185(m)	>20	<b>127</b>	<b>A</b> 89	
Nickel	ppm	ASTM D5185(m)	>15	<b>4</b> 0	17	
Titanium	ppm	ASTM D5185(m)		<1	<1	
Silver	ppm	ASTM D5185(m)	>5	<1	0	
Aluminum	ppm	ASTM D5185(m)	>25	<b>△</b> 68	<u></u> ▲ 64	
Lead	ppm	ASTM D5185(m)	>20000	7530	5652	
Copper	ppm	ASTM D5185(m)	>25	12	12	
Tin	ppm	ASTM D5185(m)	>30	0	2	
Antimony	ppm	ASTM D5185(m)		<1	<1	
Vanadium	ppm	ASTM D5185(m)		0	0	
Beryllium	ppm	ASTM D5185(m)		0	0	
Cadmium	ppm	ASTM D5185(m)		<1	2	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1	<1	
Barium	ppm	ASTM D5185(m)	0	0	0	
Molybdenum	ppm	ASTM D5185(m)		0	<1	
Manganese	ppm	ASTM D5185(m)		0	0	
Magnesium	ppm	ASTM D5185(m)	0	1	3	
Calcium	ppm	ASTM D5185(m)		4	6	
Phosphorus	ppm	ASTM D5185(m)	0	240	1187	
Zinc	ppm	ASTM D5185(m)	0	5	9	
Sulfur	ppm	ASTM D5185(m)	3800	2828	1813	
Lithium	ppm	ASTM D5185(m)		<1	<1	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	11	8	
Sodium	ppm	ASTM D5185(m)		<1	<1	
Potassium	ppm	ASTM D5185(m)	>20	0	<1	



# **OIL ANALYSIS REPORT**





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number** 

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : 02603184

: WC0844054 : 5696269

Recieved Diagnosed

: 14 Dec 2023 : 15 Dec 2023 Diagnostician : Kevin Marson

Test Package : AVI 1 (Additional Tests: PQ)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

**ITPS Canada** 2465 Aviation Lane,, Unit 1 London, ON **CA N5V 3Z9** 

Contact: Ryan Gomes

ryan.gomes@itpscanada.com T:

Report Id: ITPLON [WCAMIS] 02603184 (Generated: 12/15/2023 14:35:36) Rev: 1

Contact/Location: Ryan Gomes - ITPLON

F: